

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4701)

-----

Set a cedar post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd 1/4 S on W face, from which

A fir, 48" dia., bears N.25°E., 4 lks., mkd: 1/4 S BT.

A fir, 36" dia., bears N.20 1/2°W., 65 lks., mkd: 1/4 S BT.

BLM resurvey by James E. Jelly & Jack W. Bowder, Cadastral Surveyors, under Group No. 763, surveyed April 1972 - (DCSO records Vol. 36 Page(s) 14872-3)

-----

Point for the 1/4 sec. cor. of secs. 19 & 20, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 24" in the ground with brass cap marked:

T26S R8W  
          1/4  
S 19 | S 20  
      1972

from which

A fir, 11" dia., bears N.67°E., 30 lks., mkd: 1/4 S20 BT.

A fir, 13" dia., bears N.63°W., 38 lks., mkd: 1/4 S19 BT.

Set a 5 ft. steel fence post alongside the iron post.

Tony Hostetter - For: Weyerhaeuser - 7/2017 - M173-54

-----

Found - 1972 BLM brass cap, 4" out of ground as described by Jelly and Bowder (DSCO records Volume 36, Pg 14872-3. From which:

22" Fir, 1974 BT tag, bears N.67°E., 19.8 ft to center.

16" Fir stump, no marks, bears N.63°W., 25.1 ft to center.

New BTs- 10" Hemlock, scribed "S20 1/4 BT", BT tag, bears N.88°E., 13.0 ft to spike.

11" Hemlock, scribed "S19 1/4 BT", BT tag, bears; S.75°W., 6.3 ft to spike.