

TOWNSHIP 27 RANGE 01E POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 26, 35, & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Otto L. Draper, US Transitman, under Special Instructions dated Dec. 24, 1920 - (DCSO records Vol. 23 Page(s) 9870)

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 25, 26, 35, & 36, with brass cap mkd

T27S R1E
S 26|S 25
S 35|S 36
1927

from which

- A fir, 12" dia. bears N.27°E., 55 lks mkd: T27S R1E S25 BT
- A hemlock, 24" dia., bears S.60°E., 15 lks., mkd: T27S R1E S36 BT.
- A pine, 18" dia., bears S.35°W., 51 lks., mkd: T27S R1E S35 BT.
- A fir, 12" dia., bears N.39½°W., 55 lks., mkd: T27S R1E S26 BT.

Douglas Co. Surveyors Office - Larry Monrean Deputy - Janet Lundeen - Stephen Flause - June 12, 1985 - C.S. File 62/28-4

Found - 1927 US GLO cap, properly marked. The cap and post lean slightly NE. No sign of cat damage or disturbance.

USFS requested we renew this corner as the monument was destroyed. We saw flagging on ground and found cap by kicking 2" of dirt from top.

Monument is firmly set.

12" fir (now 13" and fallen) bears N.27°E., 36.3 ft. fragmentary scribing and open rotten blaze.

24" hemlock (now 31') bears S.60°E., 9.9 ft. visible and partially healed single blaze faces N.85°W. - some scribing visible "30 BT"

18" pine (now 19" dead snag" bears S.35°W., 34.4 ft. (Rec. 33.7') Unhealed blaze shows "LTS R1E S35 BT".

12" fir (now 22") bears N.41°W., 36.3 ft. (Rec. N.39½°W.) Heal(blaze - no visible scribing.

10" W.Fir bears S.67°W., 36.2 ft. scar facing corner. No scribing visible. It has a forest service tag.

New BTs- 16" W.Fir bears S.55½°W., 43.4 ft. scribed "T27S R1E S35 CSBT".

11" G.Fir bears N.86°E., 20.9 ft. scribed "T27S R1E S25 CSBT".