

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO records Vol. 11 Page(s) 4824)

The point for ¼ sec. cor. falls upon a rock in place, 2x1x1 ft. above ground on which cut a cross (X) at the exact cor. point for ¼ sec. cor. mkd ¼ on N face, from which
An Alder, 10" dia., bears N.81½°E., 46 lks., mkd: ¼ S22 BT
A cedar, 18" dia., bears S.15°W., 17 lks., mkd: ¼ S27 BT.

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - Nov. 1969 & Dec. 1970 - C.S. File 54/94

Reported as not found
Dec. 1969
Found E-W blazed line. This cor. very close to creek, probably washed out. 1 cedar BT 1 alder BT.
Jan. 1970
Looked for a sec. time. We brought line in from West went down into creek and still fd. no trace of ¼ cor; which had good calls on both sides of it note: the BTs were 10: alder & 18" cedar.