

TOWNSHIP 27 RANGE 02E POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Cor. Secs. 33 & 34 South

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Lincoln Wilkes, USCE, under Group No. 62, Special Instructions dated Dec. 21, 1920, surveyed Sept 1926/Aug. 1927 - (DCSO records Vol. 24 Page(s) 10373

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for standard cor. of secs. 33 & 34, with brass cap mkd:

S C
T27S | R2E
S 33 | S 34

1927

from which

A fir, 40" dia., bears N.50°E., 16 lks., mkd: T27S R2E S34
SC BT.

A fir, 40" dia., bears N.32½°W., 73 lks., mkd: T27S R2E
S33 SC BT.

Note: See GLO Survey by Samuel C. Flint, Under Contract #473, dated June 5, 1883 (DCSO Records Vol. 24 Page(s) 10358-9) for orig. sec. corner that was destroyed by Lincoln Wilkes