

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 30, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4931)

NOTE: There is a hand written note, in red, on the scanned copy of the orig. line notes on the internet (OR-R0483 PG 0364.00) stating "This cor. refers to Sec. 30 only" See G.L.O. Letter "E" 311250 JB dated Sept. 10, 1913)
West on sectional correction line, bet. secs. 30 & 31
40.00 chs
Set a hemlock post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S30 on North & 31 on South face; from which
 A hemlock, 30" dia., bears N.46°W., 19 lks., mkd: ¼ S30 BT
 A chinquapin, 6" dia., bears S.66°50'W., 23 lks., mkd: ¼ S31 BT.
42.85 chs.
Derrick ¼ sec. cor. which I now destroy, bears North 130 lks.
Note - We have no record of Derrick setting this corner.
 JC DCSO 9/2008

Thomas E. Shrum, Jr. - For: US Plywood Corp. - Nov. 1962 - C.S. File 51/254-7

Found - Truck Axle. Axle set by me in 1954 from orig. BTs which have subsequently been destroyed. I now scribe new references.
Set - 20" D.Fir stump N.52½°E., 36.7 ft. mkd: ¼ S30 BT.
 18" Hemlock stump, S.23°W., 72.8 ft. mkd: ¼ S31 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones - V. Perron - Nov. 1968 - C.S. File 54/40-131

Found - Truck axle at corner point, properly marked in 1962. Orig. 30", now 34" Hemlock (decaying stump) N.46°W., 12.5 ft. scribe visible.
 20" D.Fir stump N.52½°E., 36.7 ft. scribed & alum. tag #4287.
 SW BT stump, turned out & lying face down.
Set - 6 ft. steel fence post alongside axle.
New BT - 4" D.Fir N.57°E., 36.0 ft. mkd: "S30 CS BT"
 No other trees available. This corner lies 15 ft. E of creek course N & approx. 400 ft E of rd N & S

continued next page

1

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 30, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ronald Geisler, Champion International Corp. - June/Aug. 1985
- M90-71

Found - A 1954 truck axle set by Shrum, LS 1706, and the following accessories;
BTs - Orig. Hemlock stump, bears N.46°W., 12.5 ft. No scribing found.
24" Fir stump, bears N.52½°E., 36.1 ft. (Rec. 36.7 ft.) Scribing visible. (1962)
13" Fir, bears N.57°E., 35.7 ft. (Rec. 36.0 ft.) Closed face. (1968)
New BT - 9" Fir, bears S.48°W., 14.9 ft. Scribed ¼ S31 BT.

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCS0 records Vol. 56 Page(s) 22002)

The ¼ sec. cor. of sec. 30 only, remonumented by Shrum, in 1954, from original evidence no longer in existence, perpetuated by himself in 1962, further perpetuated by the Douglas County Surveyors Office in 1968, further perpetuated by Geisler, in 1985, monumented with a truck axle, 1 3/8" dia., firmly set, projecting 3" above ground, with 5½" dia. flange on top, (properly) mkd.
from which the remains of an original bearing tree
A decayed stump, size and species indeterminate, bears N.46°W., 12.5 ft., no marks visible.
and remains of a bearing tree mkd. by Shrum in 1962
A fir stump, size indeterminate, bears N.49°E., 35.6 ft., with scribe marks ¼ S30 BT visible on decayed face.
and a BT mkd. by the Douglas County Surveyors Office
A fir, 20" dia., bears N.54½°E., 35.3 ft., with a healed blaze.
and a bearing tree mkd. by Geisler
A fir, 15" dia., bears S.47°W., 14.9 ft., with a healed double blaze.
(Note: Marginal comments in Wygant's 1911 field notes indicate "This cor. refers to Sec. 30 only".)