

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4930)

West on sectional correction line bet. secs. 29 & 32
40.00 chs. Set a hemlock post, 3 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S29 on North & 32 on South faces; from which
 A cedar, 12" dia., bears N.50°E., 17 lks., mkd: 1/4 S29 BT.
 A cedar, 6" dia., bears S.36°30'W., 29 lks., mkd: 1/4 S32 BT
41.00 chs.
Derricks 1/4 sec. cor. which I now destroy bears North 350 lks.
Note - We have no record of Derrick setting this corner.
 JC DCSO 9/2008

Thomas E. Shrum, Jr. - For: US Plywood Corp. - Nov. 1962 - C.S. File 51/254-5

Found - 15" cedar, N.50°E., 11.2 ft. rescribed 1/4 S29 BT.
 9" cedar, S.36°W., 19.2 ft. mkd. 1/4 S32 BT.
Set - 2 1/2" alum. cap.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage - V. Perron - Oct. 1968 - C.S. File 54/40-96

Found - 2 1/2" Alum Cap, firmly set & properly mkd.
 12", now 16" Cedar, down, N.50°E. 11.2 ft., old scribe visible & new scribe visible.
 6", now 10" Cedar, alive, S.36°W., 19.2 ft., scribe visible on nearly healed blaze.
Set - 6 ft Steel Fence post alongside alum. cap
New BT - 8" hemlock, S.20°E., 31.0 ft. mkd: 1/4 S32 CS BT.
 No other trees near north of corner in section 29.
Corner lies on moderate northerly slope in clear cut unit.

Romanso E. Ware & Ronald Quimby - For: US Forest Service - July 1980 - M79-49

Found - Alum, cap on 1" I.P. mkd. USPC Prop. Cor. T27S R2W
 1/4 S29 S32 RE 4287.
 18" Cedar N.50°E., 11.2 ft. vis. scribe, dead & down
 12" Cedar S.36°W., 19.1 ft. Good scar, dead & down.
 Metal post at corner.
New BTs- 7" D.Fir, S.64°E., 43.4 ft. "1/4 S32 BT"
 7" D.Fir, N.12°E., 34.4 ft. "1/4 S29 BT"
Brass washers marked RLS 1005 set in BT faces.
Set - Post & sign 2.0 ft. North.

Cont.

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 22000-1)

The ¼ sec. cor. of secs. 29 and 32, remonumented by Shrum, in 1962, perpetuated by the Douglas County Surveyors Office in 1968, and further perpetuated by Ware and Quimby in 1980, monumented with an iron post, 1" dia., firmly set, projecting 7" above ground, with aluminum cap (properly) mkd.

from which the remains of the original bearing trees

A roothole bears N.50°E., 11.2 ft., with fallen cedar trunk, 16" dia., lying alongside, scribe marks ¼ S29 BT visible on an unhealed blaze. (rescribed by Shrum)

A cedar stump, 11" dia., bears S.36½°W., 19.1 ft., with fallen trunk lying alongside, with a healed blaze.

and remains of a BT mkd. by the Douglas Co Surveyors Office

A sawed hemlock stump, 9" dia., bears S.22°E., 30.2 ft., with fallen trunk lying alongside, fragmentary scribe marks visible on a partially healed blaze.

and bearing trees mkd. by Ware and Quimby

A fir, 18" dia., bears N.13¼°E., 33.8 ft., with a healed blaze.

A fir, 17" dia., bears S.56¼°W., 42.7 ft., with a healed blaze.