

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4927)

West between Secs. 27 & 34
39.00 chs

Derrick 1/4 sec. cor., which I now destroy bears N 3.00 chs.
Note - We have no record of Derrick setting this corner.
JC DCSO 8/2008

40.00 chs
Set Yew post, 3 ft. long 4" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S27 on N & 34 on south face; from which
A fir, 28" dia., bears N.67°50'E., 14 lks., mkd: 1/4 S27 BT.
A hemlock, 24" dia. bears S.54°13'W. 34 lks. mkd: 1/4 S34 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 5/1969 - C.S. File 54/40-165

Reported as not fd.
Old logging no OBTs fd.

Ronald A. Quimby, LS #1654 & Romanso E. Ware, LS #1005 - For: US Forest Service - May 1980 - M79-45

Found - 1" iron pipe with alum cap mkd: "USPC PROP COR. 1/4 S27 S34 RE 4287" (Not of rec.)
22" Fir stump N.68°E., 9.2 ft. (vis. scribe)
20" Fir stump rotted S.54°W., 22.4 ft. (vis. scribe)
1 1/4" iron pipe 0.1 ft. South
New BTs- 6" D.Fir N.32°E., 7.9 ft. scribed "1/4 S27 BT"
8" D.Fir S.22°W., 25.8 ft. scribed "1/4 S34 BT"
Set post & sign 3.0 ft. north.
Brass washers mkd. RLS 1654 set in BT faces.