

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

from which
A fir, 15" dia., bears N.19°E., 247 lks., mkd. ¼ S2 BT.
A cedar, 18" dia., bears S.44½°E., 201 lks., mkd. S11 BT.
Deposit local corner material alongside iron post.

Fd. Ok 4/28/1976 - C.S. 59/8-25 - Co. Surveyor.

BLM dependent resurvey by Lance J. Bishop & Wayne L. Rogers, Cadastral Surveyors, under Group #1189, surveyed May/July 1984 - (DCSO records Vol. 47 Page(s) 17967-8)

The ¼ sec. cor. of secs. 2 & 11, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.
from which the remains of BTs mkd. by Frear, in 1943
A cedar stump, 18" dia., bears S.86°E., 98 lks., with scribe marks ¼ S2 BT visible on partially healed blaze.
A W.Oak, 15" dia., bears S.8¼°W., 180 lks., with healed double blaze.
and the remains of bearing trees mkd. by Corbin
A fir stump, 15" dia., bears N.19°E., 240 lks., with healed blaze. (Record, 247 lks.)
A cedar stump, 20" dia., bears S.44½°E., 201 lks., with healed blaze.
and new bearing trees
A fir, 6" dia., bears S.65½°E., 38½ lks., mkd. ¼ S11 BT.
A cedar, 11" dia., bears N.31½°W., 50½ lks., mkd. ¼ S2 BT.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Dec. 7, 1984 - C.S. File 62/21-25

NOT FD - Rock mound (1943) no longer evident.
¾" iron bar, pin or pipe as recorded in 1943, 1955 & 1958 dependent resurvey is not found.
Orig. BTs searched for, not found.
BTs from 1943 searched for, not found

Found - 1958 BLM 3¼" disk on a 2½" IP properly mkd. is firmly set & protrudes 6" above ground.
At west edge of BLM monument, a 5/8" dia., IR is firmly set and protrudes 18" above ground.
10" W.Oak, now a 14" DBH W.Oak bears S.6¼°W., 119.6 ft. (Rec. S.08¼°W., 119.0 ft.) This tree has a well healed single blaze, no scribing visible.
14" cedar, now a 15" dia., 4 ft. tall cedar stump with the scribing ¼ cor 1 sec 2 BT visible in an opened single blaze, bears S.86°E., 64.5 ft. (Rec. S.89°E., 64.5 ft)

continued next page

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

15" Fir, now a 15" dia. 6 ft. tall fir stump with a well healed single blaze, no scribing visible, bears N.19°E., 163.0 ft. (per rec). (1958)
18" Cedar now a 24" dia. 2 ft tall cedar stump with a well healed single blaze bears S.44½°E., 132.7 ft. (1958)
New BTs from as yet unrecorded BLM survey done in 1984:
6" DBH D.Fir with the scribing ¼ S11 BT visible in a partially healed single blaze, bears S.65½°E., 25.4 ft.
An 11" DBH cedar with the scribing ¼ S2 BT visible in a partially healed single blaze bears N.31½°W., 33.8 ft.
Monument lies near top of cut bank on north side of Little River Rd. approx. 0.2 miles southeast of Little River Store. (Cavitt Creek area.)

CS 63/34-19, 2/5/1986
Fd. Ok by Mark Heimburger, 3/1994 M118-54
Fd. Ok by Don Bentz, 3/1995 Vol. 18 Pg. 41
Fd. Ok by Wayne Rogers, 5/1999 1999-0052
Fd. Ok by Kris DeGroot, 10/2001 2001-0083

Fd OK: BC, 3 live BTS (New Tags nailed) 5/8" IR by DCS0, SJF & JL 2/8/2019 C.S. File 67/46-2
LAT: 43°14'33.69"N LONG: 123°01'11.60"W (ADDED 2/14/2023 - SEE CS 67/55-21)