

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882  
- (DCSO records Vol. 12 Page(s) 4858)(and dup. pg. #4981)  
-----

Set Maple post 3 ft. long, 3" sq., firmly in the ground for  
¼ sec. cor. marked ¼ S on E. and W. faces, from which  
A Fir 14" dia., bears N.15°W., 8 lks. dist. mkd. ¼ S BT.  
An Alder 6" dia., bears S.80°E., 25 lks. dist. mkd. ¼ S  
BT.

Thomas E. Shrum, Jr. - For: U.S. Plywood Corp. - Jan. 1961 -  
C.S. File 51/174 and M 11-78 and M 11-51  
-----

Found 1/2" Iron rod and 20" D.Fir, N.15°W., 5.3 ft.  
New BTs- 10" D.Fir, S.57°W., 26.5 ft.  
6" D.Fir, S.11°E., 21.0 ft.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Nov. 6, 1968 - C.S. File 54/40-108  
-----

Found - 1/2" I. rod and BTs as recorded by Shrum.  
10" now 12" D.Fir, alive, S.57°W., 26.5 ft. blaze  
nearly healed over.  
6" now 8" D.Fir alive, S.11°E., 21.0 ft. scribe  
visible on partially healed blaze.  
Orig. NW. BT, now burned out stump, no scribe, only  
opening facing corner point.  
Set Brass cap at cor. mkd: County Surveyors Office  
(Reset I.R. alongside) T 27 S  
R3W ¼ S12 | S 7 R2W  
1968  
This cor. lies on N-S fence line 50 ft. S. of left bank  
Little River.

Fd. and Used in BLM resurvey by Wayne L. Rogers, Cadastral  
Surveyor, Group #983, surveyed May/Aug. 1979 - (DCSO records  
Vol. 43 Page(s) 16912-13)

Douglas Co. Surveyors Office - Larry E. Monrean, LS #1830 -  
Smith and Flause, crew - Dec. 13, 1984 - C.S. File 62/21-24  
-----

Found - 1968 DCSO brass disk on a I.P. protruding 8" above  
a 2½" dia., mound of stone, properly marked.  
No visible evidence found of 1/2" I.R. noted in 1961  
and 1966. No evidence found of 3/4" I.R. set in  
1947. (Per C.S. File 40/56)

(Cont. Next Page)

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 12; and S. 7, T27-2

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

14" now a 28" dia. 3 ft. high rotted and burnt stump. No scribing found, bears N.36°W., 7.8 ft. to center. (Rec. N.15°W., 5.3 ft.) Orig. BT.  
10" now a 16" D.Fir with a well healed single blaze bears S.55½°W., 25.7 ft. which agrees with 1979 BLM resurvey. (Rec. S.57°W., 26.5 ft.)  
6" now a 14" D.Fir with a well healed single blaze bears S.13°E., 20.8 ft. which agrees with 1979 BLM resurvey. (Rec. S.11°E., 21.0 ft.)  
New BTs- 8" D.Fir double blaze and scribed "¼ S7 CS BT" bears S.51°E., 25.6 ft.  
13" D.Fir double blaze and scribed "¼ S12 CS BT" bears N.25½°W., 38.6 ft.  
Corner lies approx. 50 ft. South of the left bank of Little River.