

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 31; and 6 of T.28-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, Contract #44 dated May 30, 1854
(DCSO records, Volume 12 Page 5032)

Set 1/4 sec. post, from which
A B.Oak 6" dia. bears N.80°W., 100 lks. dist.
A R.Fir 10" dia. bears S.60°E., 180 lks. dist

Remeasurement of Sixth Standard Parallel, Addison R. Flint,
Contract #56 dated March 1, 1855 (DCSO Records, Volume 12
Page 5046)

Set 1/4 Sec. post, from which
A W.Oak 5" dia. bears S.35°W., 24 lks. dist.
A W.Oak, 6" dia. bears N.68°E., 59 lks. dist.

Exteriors of T.28-4, surveyed by W.H. Byars, Contract #376
dated January 22, 1881 (DCSO records, Volume 12 Page 5079)

Intersect 1/4 sec. cor. and set new post as per instructions,
from which:
A W.Oak 5" dia. bears S.35°W., 24 lks. dist.
A W.Oak 6" dia. bears N.68°E., 59 lks. dist.

C.C. Boyer, Deputy Co. Surveyor, June, 1913 For: L. Hatfield
Volume 2 Page 174 - F.B. 35 Pages 3-11

I reestablished from original BT, in Section 31. As this tree
is small and the marks are partly obliterated, I remarked this
corner as follows -
Set - W.Oak post 4x4x36", mkd: 1/4 S S6 28 S4, from which W.Oak
6" dia. mkd C.S. 1/4 S S6 BT bears S.28°W., 68 lks.
Red Fir 14" dia. marked C.S. 1/4 S. S.6 B.T. bears
N.72°E., 38 lks.

James W. Byron, Deputy Surveyor - M. Godfrey; S.A. Bilow
January 23, 1959 - C.S. File 49/130-14

Found - Boyer's 14" now 24" Fir stump N.72°W., 25.1 ft., I
open & find good scribing "S 1/4".
Do not find Boyer's SW BT or either orig. BT.
Set brass cap at corner mkd: County Surveyor's Office, 1959
1/4 S 31 T27S R4W
S 6 T28S
New BTs: 14" R.Fir bears N.31°E., 96.8 ft. scribed 1/4 S31 CSBT
14" R.Fir bears S.77°W., 38.5 ft. scribed 1/4 S6 CS
BT (Location sketch in C.S. File)

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 31; and 6 of T. 28-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 11/17/1999 - C.S. File 66/13-11

Found - DCS0 BC/IP, properly mkd., protrudes 13" above
ground.
14" now 23" dia., D.Fir with a fully healed double
blaze bears N.31°E., 96.8 ft. 1959
14" now down & badly rotted D.Fir bears S.77°W.,
38.5 ft. 1959
No other BTs found.
New BTs- 7" dia., B.Oak double blazed & scribed "¼ S31 CS BT"
bears N.70½°E. 19.0 ft.
8" dia., Madrone bark scribed "X CS BT" bears
S.56°W., 12.2 ft.
Corner lies along easterly edge of cat road.