

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Addison R. Flint, Contract #56 dated March, 1855  
(DCSO Records, Volume 12 Pages 5053-54)

-----  
Set 1/4 sec. post, from which  
    A Laurel 5" dia. bears S.15°E., 36 lks. dist.  
    A Willow 2" dia. bears North 18 lks. dist.

Bureau of Land Management Dependent Resurvey by James Jelley  
under Group No. 700 - Survey April 1970 (DCSO records, Volume  
35 Page 14461)

-----  
Point for the 1/4 sec. cor. of secs. 26 and 35, at proportionate  
distance; there is no remaining evidence of the original  
corner. Set an iron post, 28" long, 2 1/2" dia. 24" in the  
ground with brass cap marked:

S 26  
    1/4 S 35  
T 27 S R 4 W  
1970

from which  
    A Fir 6" dia. bears N.50°W., 75 1/2 lks. marked 1/4 S26 BT.  
    A Fir 7" dia. bears S.33 1/2°E., 21 lks. marked 1/4 S35 BT.

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda -  
3/27/2008 - C.S. File 67/25-26

-----  
Found - 1970 BLM dependent resurvey, 3 1/2" dia., brass cap  
(properly) marked on a 2 1/2" OD iron pipe, firmly  
set & protruding approx. 6" above ground.  
Evidence of one 1970 BT fd. 7" now 13" DBH 6 ft.  
tall D.Fir stump with a fully healed double  
blaze bears S.33 1/2°E., 13.9 ft. (as per record)  
NW BT gone, falls in edge of newer dirt road.

New - DCSO established these new BTs in 2000 but renewal  
was not recorded then:  
12" DBH I.Cedar which was double blazed & scribed 1/4  
S26 CS BT (now healed) bears N.86°E., 15.4 ft.  
14" DBH I.Cedar which was double blazed & scribed 1/4  
S35 CS BT (now healed) bears S.11°E., 16.8 ft.  
20" DBH D.Fir which was double blazed & scribed 1/4  
S26 CS BT (now healed) bears N.20°W., 36.0 ft.

Note - Monument is on relatively large bench area;  
partially logged some years ago.  
Compass decl. 16 1/4°E.