

PRIMARY CORNER DESCRIPTION Sec cor for 24 & 25 only (West)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

(Original Corner for 23, 24, 25 & 26 set by Addison Flint, Contract #56, 1855 - See DCSO records, Volume 12 Page 5050)

-----

Set post, cor. to secs. 23, 24, 25 & 26, from which

- A Laurel 3" dia. bears N.22°E., 11 lks. dist.
- A Laurel 3" dia. bears N.36°W., 5 lks. dist.
- A Laurel 3" dia. bears S.85°E., 5 lks. dist.
- A Laurel 3" dia. bears S.57°W., 25 lks. dist.

GLO resurvey and retracement by Elmer F. Strickler, under Special Instructions, dated January 22, 1917 (DCSO records Volume 12 Page 5085)

-----

Set an iron post, 3 ft. long 2" diam. 24" in the ground, for cor. of secs. 24 & 25, with brass cap attached marked:

T27S
S24
S25
R4W
1917

from which

- A Fir 12" dia. bears N.61°30'E., 16 lks. dist. marked T27S R4W S24 BT.
- A Fir 20" dia. bears S.40°15'E., 38 lks. dist. marked T27S R4W S25 BT.

This cor. is 60 ft. above the creek.

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Stone; Darby; Halterman - October 1963 - C.S. File 53/33-13

-----

Found - Pipe with brass cap set in 1917 survey.

- 12" Fir N.61½°E., 10.6 ft., now splintered snag, badly burned old face. No scribing left.
- 20" Fir S.40¼°E., 25.1 ft., now uprooted & dead.

New BTs-

- 4" Madrone S.76°E., 21.5 ft. mkd. S25 CS BT.
- 25" I.Cedar N.63°E. 153.6' mkd. T27S R4W S24CS BT.

Harvey Christensen - June 7, 1999, Recorded 11/13/2001 - C.S. File 65/40-1

-----

Found - 2½" dia., GLO brass cap on 2" iron pipe, protruding 10" above ground level near fence corner.

- 33" Cedar N.63°E., 153.6' to ctr. with healed blaze.
- 11" Madrone S.76°E. 21.5' to ctr. with healed blaze.

New -

- 10" D.Fir N.22°W., 11.7' to ctr. blazed & scribed "X" at breast height & "BT" at base.
- 12" D.Fir S.30½°W., 18.7' to ctr. blazed & scribed "X" at breast height & "BT" at base.

continued next page

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 600277

PRIMARY CORNER DESCRIPTION Sec cor for 24 & 25 only (West)

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

Note - This monument falls 2' North of fence corner, fence lines running East & South.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/23/2000 - C.S. File 66/14-34

Fd. OK - 2 BTs not in renewal found:

11" D.Fir with an unhealed double blaze "X BT" per tag, bears N.21°W., 11.7 ft.

12" D.Fir with an unhealed double blaze "X BT" per tag, S.30½°W., 18.7 ft.

Tags dated 6/97

No measurements made at corner.

Note - See 6/1999 corner report by Harvey Christensen filed 11/13/2001 (DCSO 11/14/2001 JC)

DCSO-GIS Corner visitation - 3/8/2006 - Typed: 1/27/2011 - C.S. File 67/33-1

Monument - GLO/BLM 2½" BC/IP

Comment - OK

BLM Dependent resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2189 surveyed June/Sept 2008 - (DCSO records Vol. 57 Pgs 22500-1)

The cor. of secs. 24 and 25 only, perpetuated by Godfrey, in 1963, further perpetuated by Christensen, in 1999, monumented with an iron post, 2" dia., firmly set, projecting 18" above the ground, with brass cap (properly) mkd.

A madrone, 12" dia., bears S.76°E., 21.8 ft., with a healed double blaze.

and bearing trees mkd. by Christensen

A fir, 15" dia., bears S.29°W., 18.8 ft., with a healed blaze.

A fir, 11" dia., bears N.22¾°W., 11.6 ft., with a healed double blaze.