

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 23 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 12 Page 5050)

Set ¼ sec. post for 23 and 24, from which
A R.Fir 16" dia. bears N.87°E., 7 lks. dist.
A Maple 6" dia. bears S.45°W., 12 lks. dist.

Resurvey & Retracement, GLO, Elmer F. Strickler, under Special
Instructions dated Jan. 22, 1917 (DCSO records, Volume 12 Page
5086)

Set a limestone, 14x9x5", 10" in the ground, for ¼ cor. of
Sec. 23 only, marked ¼ on W. face, from which
A Fir 30" dia. bears S.60°W., 16 lks. dist. marked
¼ S 23 B T.
A Fir 36" dia. bears N.71°W., 60 lks. dist. marked
¼ S 23 B T.

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone
November 1963 - C.S. File 53/33-34

Found - 42" Fir S.60°W., 10.6 ft., cut open & found good
scribing "S2". Tree alive & in good condition.
Did not find Rock at corner, lies on very steep
north slope.
Jagged remnants of Fir stump, (uprooted tree 100 ft.
downhill), N.71°W., 39.6 ft.
At corner drove a 3/4" Iron pipe.
New BT - 22" D.Fir N.62½°W., 52.3 ft. mkd: ¼ S23 CS BT.
Corner is approx. 70 ft. North of West ¼ cor. to Sec. 24.

Dependent Resurvey, Bureau of Land Management, Glenn Baughman
Contract #52500-CT5-1116, Oct.-Dec. 1975 (DCSO records, Volume
39 Page 15789)

The ¼ sec. cor. of sec. 23 only, perpetuated & recorded by
James Byron, Co. Surveyor in 1959 (our notes say 1963, V.L.)
monumented with an I.P. ¾" dia. firmly set, protruding 14"
above ground, from which the remains of the bearing trees mkd.
by Strickler;

(Continued Next Page -)

