

PRIMARY CORNER DESCRIPTION SE cor. Daniel Barnes DLC #49

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint - Contract #28 - July, 1854  
-----

Set - Post

BTs - A W. Oak 12" dia. bears S.75°E., 39 lks.

A B. Oak 15" dia. bears N.18°W., 325 lks.

H.L. Eppstein, Co. Surveyor - Wit. Bert Lane; Milton Palm;  
August 5, 1932 - (no record source found - see "old" corner  
book, Page 88) (Tied to in Vol. 4 Pg. 53)  
-----

Set - Iron pipe for corner from old W. Oak BT.

Marked - A 14" W. Oak S.71°30"E., 109 ft. for new witness  
tree.

Bruce Shaner - For: Henry Flury - May 1966 - M33-2  
-----

Found - 3/4" iron rod, from which a

30" W.Oak BT with old scribes visible bears S.75°E.,  
25.7 ft.

24" W.Oak BT with old faces bears S.71½°E., 109.0  
ft.

Doug. County Surveyors Office - Randall W. Smith & Stephen J.  
Flause - April 20, 1993 - C.S. File 64/41-18  
-----

Found - 1" dia. steel axle, protrudes 1" above ground, leans  
0.5' south of plumb. Source unknown. I.P. set in  
1932 not found.

12" now 35" dia. W.Oak with a previously opened now  
rehealed single blaze, bears S.80°E., 25.7'. (rec  
S.75°E., 25.7') Orig. BT.

Orig. N.W. BT is gone.

14" now 27" dia. W.Oak with a fully healed double  
blaze, bears S.68°E., 109.0' (rec. S.71½°E.,  
109.0') 1932 DCSO renewal.

New - 6" dia. W.Oak double blazed and scribed "SE DLC 49  
CS BT" bears N.54½°W., 22.7'.

17" dia. B.Oak double blazed and scribed "SE DLC 49  
CS BT" bears S.72¼°W., 46.3'

Note - We perpetuated a locally accepted monument.