

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Corner for Secs 30 and 31

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April 1853

-----  
Set ¼ Sec. Post, from which  
    A W. Oak, 11" dia. bears N.6¼°E., 454 lks. dist.  
    A W. Oak, 12" dia., bears S.17°E., 334 lks. dist.

On S.E.R.A. Project - D. Wolford - Vol. 4 Pgs. 50-58  
1934-37-38

-----  
Found - Iron pipe by old corner post. One original BT,  
          other gone.  
New BTs - 8" W.Oak, N.10°W., 69.0 ft.  
          6" W.Oak, South, 190 ft.

Douglas County Surveyors Office - James W. Byron Deputy,  
Milo Godfrey; C. Putnam - Nov. 10, 1959 - C.S. 49/62-7

-----  
Found - ¾" iron pipe at corner.  
          Original 12" now 30" W.Oak, N.6¼°E., 299.6 ft.,  
          shows old face, now rotted. No scribing  
          found, checks bearing and distance.  
          No trace of original SE BT found.  
          Also find now 15" W.O. bears N.6°W., 68.7 ft.,  
          shows good scribing "S30 CS BT". Scribed about  
          30 years ago. Probably scribed 1934.  
New BTs - Rescribed 15" W.O. N.6°W., 68.7 ft. ¼ S30 CSBT.  
          8" W. Oak bears S.2°W., 189.3 ft. scribed ¼ S31  
          CS BT.  
Note: N-S fence 15 ft. east.

Douglas County Surveyors Office - Randall Smith; Stephen  
Flause - Jan. 24, 1990 - C.S. 64/5-6

-----  
Found - A ¾" I.D. iron pipe protruding 3" above ground.  
          (Source unknown) See previous reports.  
          11" now 26" dia. W. Oak with a previously opened  
          now rehealed scar bears N.6¼°E., 299.6 ft.  
          (agrees w/rec) Original BT.  
          15" now 18" dia. W. Oak with a fully healed double  
          blaze bears N.6°W., 68.7 ft. (source unknown)  
          8" W. Oak, S.2°W., 189.3 ft. is gone.

TOWNSHIP 27 RANGE 05 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Corner for Secs 30 & 31

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

continued:

N-S fence noted in 1959 as being 15 ft. east is gone.  
Set - Found 3/4" I.P. is referenced. 3/4" I.P. is dug out and measured 24" long. A 2 3/8" dia. brass cap on a 1 3/8" O.D. x 31" long iron pipe is set at referenced position and protrudes 5" above ground. 3/4" I.P. is set along north side of BC/IP and protrudes 4" above ground.  
New BTs - 9" W. Oak double blazed and scribed "1/4 S31 CS BT" bears S.30¼°E., 183.0 ft.  
7" W. Oak double blazed and scribed "1/4 S31 CS BT" bears S.35°W., 230.0 ft.  
15" W. Oak double blazed and scribed "1/4 S30 CS BT" bears N.24°W., 97.7 ft.  
Corner lies approx 250 ft. easterly of a gravel road on an open hilly pasture.

Fd. Ok by Herm Pieske 12/2005 - M 149-68  
N 5662079.29 E 1244246.25 (OCS 27)

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause -  
4/22/2008 - C.S. File 67/25-42

-----  
Fd. BC & 3 live BTs