

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 050060

PRIMARY CORNER DESCRIPTION SE Cor. McKinney DLC #50 (WC)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

-----  
Set post from which  
    A W.Oak 8" dia. bears South 77 lks.  
    Raised mound with trench as per instructions.

Ben B. Irving; N.E. Richardson; Cliff Mabley - April 1, 1928  
Survey of Co. Rd. #13 "Old" Ren. Vol. 1

-----  
Found original BT, old surface rotted out but figures plain on reverse chip. This corner comes in present traveled portion of county road, Roseburg to Melrose. As it is planned to regrade this section soon did not set anything for corner point but marked new BTs as follows:  
    Laurel 12" dia. bears East 22 lks. scribed thru bark SE Cl. 50 C.S. B.T.  
    Black Oak 10" dia. bears N.55°E., 30 lks. blazed & scribed S.E. Cl. 50 C.S. B.T.  
Corner is located 6 ft. right of center line station 196+01 on the new road survey.

James W. Byron, Deputy - Milo Godfrey; Clete Putnam - Jan. 13, 1961 - C.S. File 49/79-10

-----  
Found - 10" now 14" B.Oak, recorded by B.B.I. 1931. We open and find good scribing.  
    East Laurel BT not found.  
Note, this corner in roadway. Witness Corner set 50 ft. west of true corner.  
Set - Brass cap at Witness Corner mkd. County Surveyor's office, 1961 Wit. Cor. 50' to S.E. D.L.C. 50 T27S R6W.  
New BTs - 9" W.Oak bears S.79°W., 19.7 ft. scribed WC DLC SE 50 CS BT.  
    8" B.Oak bears N.10½°W., 30.0 ft. scribed WC DLC SE 50 CS BT.

Douglas Co. Surveyors Office - V.R. Tracy & crew - Feb. 10, 1970 (Full report added 5/26/2022) - C.S. 49/79-94

-----  
Found - 1961 C.S. brass cap in place & mkd: "COUNTY SURVEYORS OFFICE 1961 WIT COR SE COR DLC 50 | 50'EAST TO COR. T27S R6W" and BTs as follows:  
    9" now 10" W.Oak S.79°W., 19.7 ft., alive - healed blaze - tagged  
continued next page

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 050060

PRIMARY CORNER DESCRIPTION SE Cor. McKinney DLC #50 (WC)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

8" B.O. N.10½°W., 30.0 ft., down scribe visible on unhealed blaze on underside of BT.  
New BT - 12" B.Oak N.22°W., 35.2 ft. mkd. "W.C. S.E. DLC 50 C.S. BT."  
This cor. lies 10' W of top of cut bank on W side of Melrose Rd. about 150' So. of Rocky Point Curve.

Fd. OK, D. Bentz - Dec. 1991 - MLP 1991-0075

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 4/6/2017 (Filed 11/10/2021) - C.S. File 67/49-20  
-----  
Witness corner (reference monument)  
Found - A 2½" dia., DCSO 1961 brass cap on a 1" I.D. IP sitting plumb protruding 14" above ground. The brass cap of the fd monument is (properly) mkd. No orig. BTs referencing the true corner position remain.  
From the 1961 DCSO renewal 2 trees referencing the "Witness Corner"-  
A 9" W.Oak, now a 14" dia., W.Oak with a fully healed single braze; bears S.79°W., 19.7 ft. (as per record)  
An 8" B.Oak, now tipped out of position, only a roothole remains and bears N.10½°W. 30.0 ft (as per rec)  
From the 1970 DCSO renewal 1 new BT -  
A 12" B.Oak now 13" dia., B.oak with a fully healed double blaze; bears N.22°W., 35.2 ft (as per rec)  
New - An 11" dia. W.Oak scribed "SE DLC 50" "BT" on a double blaze; bears N.36½°E., 17.1 ft.  
A 15" madrone scribed "SE DLC 50" "BT" on a double blaze; bears S.21½°W., 42.6 ft.  
Note - Declination 15°E.  
BC monument situated as previously described and on a moderate ESE slope in mostly Oak woodland.