

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 057040

PRIMARY CORNER DESCRIPTION SE Cor. Champaign DLC #57

Alias 064010 Description NE Cor. DLC #64

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set Post from which

A B.Oak, 15" dia. bears South 7 lks.

A B.Oak, 6" dia. bears N.47°W., 30 lks.

Wm. Briggs - Hatfield & G. Scott, chnm. April 25, 1893

For: H & G Scott - Field Book 95 Page 90 - Vol. 1 Pg. 247

Old BT destroyed. Marked new BT, Myrtle 6" N.30°W., 37 lks.

G.R. Lecklider, Engineer - Survey for C.W. Hagen & Bessie
Smith - September 1958 - C.S. 42/393 - M 12-67

Accepted the fence corner for the northeast corner of DLC
No. 64 because of the common acceptance for many years and
it fits the conditions as well as can be expected, considering
that in most cases it is within allowable errors permitted in
the original surveys.

Set - A 5/8" x 36" rod at this point from which:

16" W.Oak bears West 13.2 ft. mkd. "DLC 64 BT"

12" Myrtle bears N.46°W., 27.3 ft. mkd. "DLC 57 BT".

Found OK March 1977, H. Northcraft - M 63-72

Doug. Co. Surveyor Office - R.B. Kimberling; P.C. Earle
June 30, 1977 - C.S. File 59/34-45

Found - 5/8" x 33" iron rod (rec. 36" long) on N-S fence
line & remains of wire fence to west.

A 16" now 20" W.Oak bears N.86°W., 13.2 ft. (rec
West) with well healed double blaze.

A 12" now 14" Myrtle bears N.46°W., 27.3 ft. with
partially healed double blaze & scribe marks
visible.

Set - Brass cap on 1" x 36" I.P. mkd. "County Surveyors
Office T27S SE Cor DLC 57 NE Cor 64 R6W 1977"

Note - No new accessories. (From N-S fence cor. to the East is
North 10.6 ft. from brass cap)

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 057040

PRIMARY CORNER DESCRIPTION SE Cor. DLC #57

Alias 064010 Description NE Cor. DLC #64

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen Flause; Shawn Means
June 19, 1980 - C.S. File 61/6-54

Found - A 1977 DCSO brass cap properly mkd. on a 1" x 30"
iron pipe firmly set & protruding 3" from
ground.

A 5/8" x 36" iron rod is set at the north east edge
of the cap. Top of I.R. is 1/2" higher than top
of brass cap.

Cap is 0.3 ft. east of corner of new fences running
north & west.

Cap is 10.6 ft. south of older fences running south
and east..

Search for orig. BTs made, none found.

Tree from 1893 not found.

A 16" now 20" W.Oak bears N.84°W., 13.2 ft. (Rec.
West 13.2 ft.) Has well healed double blaze, no
scribing visible. (1958)

A 12" now a 14" Myrtle bears N.55 1/2°W., 27.3 ft.
(rec. N.46°W., possibly mag. attraction from
fence was not adjusted for, 27.3 ft.) Has part-
ially healed double blaze with scribing "DLC 5"
visible.

Set - Existing monument at position determined by
Lecklider is perpetuated with a new accessory
as follows:

An 8" Ash tree bears N.70°E., 25.6 ft. and is
scribed "SE DLC 57 CS BT" on a double blaze.

All trees are retagged with DCSO BT tags marked with bearings
and distances as determined in this renewal.

BC & 2 BTs found OK, April, 1991, D. Bentz, MLP 1991-0040
Found Ok - Oct. 1994 - L. Dolan - 1995-0018 A&B