

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 31 & 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----  
Set ¼ sec. post, from which  
    A Y.Oak 12" dia. bears N.38°W., 31 lks. dist.  
    A Y.Oak 18" dia. bears East, 4 lks dist.

James W. Byron, Deputy County Surveyor - Milo Godfrey;  
Clete Putnam, January, 1961 - C.S. 49/79-16  
-----  
Found - Orig. 18" now down 22" Oak, East 2.6 ft. We open  
          & find good scribing "BT".  
          Orig. 12" now 30" B.O. N.38°W., 20.5 ft. shows good  
          scar. I do not open.  
          I also find ¾" I.P. at corner & under N.S. fence.  
Set - Brass cap alongside corner I.P. & mkd: County  
      Surveyor's Office, 1961 ¼ S31|S32 T27S R6W.  
New BTs - 7" W.Oak, N.28°E., 62.6 ft. scribed ¼ S32 CS BT.  
          24" B.Oak, N.37°W., 20.0 ft. scribed ¼ S31 CS BT.  
          (O.B.T.)

Found OK, Glenn Baughman, April, 1984, C.S. File 58/288

Doug. County Surveyors Office - Randall Smith-Stephen Flause.  
May 11, 1993 - C.S. File 64/43-8  
-----  
Found - 2½" dia. Brass cap on a 1½" O.D. iron pipe ,  
          protruding 20" above ground.  
          ½" I.D. iron pipe protrudes 2" above ground fd.  
          along east edge of BC/IP (source unknown)  
          12" now 25" dia. B.Oak with a fully healed double  
          blaze, bears N.37°W., 20.0 ft. (Orig. BT)  
          Orig. east BT is gone.  
          7" now 9" dia. W.Oak with a fully healed double  
          blaze, bears N.28°E., 62.6 ft. (1961 Byron)  
New Accessories -  
          8" dia. Madrone, bark scribed "CS ¼ S31 BT" bears  
          S.19°W., 10.0 ft.  
          12" dia. Ash double blazed and scribed "¼ S32 CS  
          BT" bears N.57°E., 66.7 ft.  
Note - Corner is 1 ft. west of a north-south fence line.