

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Elder & Gile, Contract #31 dated April, 1853 ----- Set ¼ sec. post, from which A Y.Oak, 16" dia. bears N.20½°W., 652 lks. A Y.Oak, 18" dia. bears S.58½°W., 237 lks.</p>
<p>James W. Byron, Deputy County Surveyor - Milo Godfrey January, 1961, C.S. File 49/79-18 ----- Found - Orig. 16" now down 40" B.Oak, N.20½°W., 430.0 ft. We open & find good scribing "¼S". No trace of original SW BT found. Note: Corner falls in County roadway. WE SET Wit. Cor. 40 ft. West. Set - Brass cap at Wit. Cor. mkd. 40' East to ¼ <u>S 9</u> County Surveyors Office, 1961 <u>S16</u> 27S R6W New BTs - 16" W.Oak bears S.28½°W., 10.6 ft. scribed WC ¼ S16 CS BT. 12" W.Oak bears N.28½°E., 13.0 ft. scribed WC ¼ S9 CS BT.</p>
<p>Found OK per G. Lang, May, 1989 - M 108-17 Found OK, B. Cap & 2 BTs, B. Rogers, 12/90, MLP 1991-0044 Fd. Ok Russell Pinard 12/2000 - M 136-24</p>
<p>DCSO-GIS Corner visitation - 4/14/2005 - Typed: 1/28/2011 - C.S. File 67/33-1 ----- Monument - 1¼" IP w/BC Comment - (needs) rehab</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 4/5/2017 (Filed 3/17/2020) - C.S. File 67/46-28 ----- Found - A 1" i.d. iron pipe by Byron, in 1961, firmly set, projecting 5" above the ground with a 2½" brass cap (properly) marked BTs for WC by Byron in 1961 - A root hole bears N.28½°E., 13.0 ft. with an uprooted and rotted 12" W.Oak alongside A 17" W.Oak bears S.28½°W., 10.6 ft. with a healed blaze. New - A ¾" iron rod per M 36-59, firmly set, projecting 2" above the ground bears N.11°21'20"E., 135.91 ft. (Rec. 136.98 ft.) A 5/8" iron rod per M 136-24 bears N.33°26'37"E., 148.49 ft. (Rec. N.32°25'35"E., 148.93 ft.)</p>

TOWNSHIP 27 RANGE 06 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - A 1½" iron bar per the 1929 County Road 13 Survey, firmly set, buried 2" below the ground bears S.19°49'58"E., 240.93 ft. (Rec. S.20°42'09"E. 241.08 per M 108-71)
M36-59 used for basis of bearing.
All bearing trees have BT tags attached. All new bearing trees have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.
Monument falls on a moderate east slope approx. 45' West of the center of County Road 13 and approx. 12.5 ft. above road elevation.
Compass decl. 15°E.