

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Pg 5260 & Vol. 13 Pg 5261)

Set ¼ sec. post, from which
An Ash 12" dia., bears N.40°W., 456 lks. dist.
An Oak 36" dia., bears S.4¼°E., 660 lks. dist.

H.L. Eppstein, Co. Surveyor - B.A. Lane; Bob Mathews; Fritzpatrick's Bros. - June 30, 1930 - M 1-73; C.S. File 14/59; 14/44; Vol. 4 Page 11

This corner was lost, so I ran line from section corner of 31 and 32 north to sec. cor. of 30, 31, 29 and 32 and then set ¼ corner by proportionate distance between. Set post in field and marked as new BTs the following:
A W.Oak 10" dia., bears S.4°E., 197.2 ft.
O.C.P. Co. Power Pole 2/18 bears S.34°W., 223.6 ft.

Doug. County Surveyors Office - James W. Byron, Deputy - M. Godfrey; S. Bilow - Dec. 23, 1957 - C.S. File 49/50-3

Found - Scribed Power Pole S.31½°W. (Rec. S.34°00'W) 223.6 ft
15" W.Oak S.4°E., 197.2 ft. shows good scar. I do not open.
Set brass cap at cor. mkd: T27S R7W S31|S32 ¼ County Surveyor Office, 1957
Tie to new power pole, RF 1 S83½°W., 137.0 ft.

1
1
A

Note: This corner removed June 17, 1960, M 18-80.

Doug. County Surveyors Office - James Byron, Deputy - M. Godfrey; C. Putnam - For: Bonneville Power, June 10, 1960 C.S. File 52/28; M 18-80

Witness corner for ¼ corner secs. 31 and 32
Set brass cap mkd: Wit. Cor. 150 South to ¼ Cor.
S31|S32 T27S R7W
County Surveyor's Office, 1960

No BTs.

Witness Corner South of ¼ Corner to Secs. 31 and 32
Set Brass cap mkd: Wit Cor. 355 ft. North to ¼ Cor.
S31|S32 T27S R7W
County Surveyors office, 1960

Scribed - 6" B.Oak N.87°W., 5.4 ft. Wit Cor. ¼ S31 CS BT.
4" W.Oak S.4°E., 15.6 ft. W.C. ¼ S32 CS BT.
Property line North 1.3 ft.

Cont.

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION WC 1/4 Cor Secs 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Doug. County Surveyors Office - Randall W. Smith & Stephen J. Flause. Mar. 30, 1993 - C.S. File 64/43-2

South Witness Corner

Found - 2½" Dia. DCSO Brass Cap on a 1½" O.D. Iron Pipe protruding 14" above ground. for southerly W.C. (mis-marked R5W)

Accessories Found -

6" now 13" dia. double trunked B.Oak with a fully healed double blaze on east trunk. Bears N.87°W., 6.1 ft. to root crown. (rec. N.87°W., 5.4' to center of east trunk.

4" now 12" dia. W.Oak with a fully healed double blaze bears S.06°E., 15.6' (rec. S.04°E., 15.6'.)

Set - DCSO BC/IP was mis-marked, changed R.5W to R.7W.

New - 3" dia. BPA Brass Cap on a 2" O.D. Iron Pipe protruding 2" above ground. Bears N.85½°W., 11.2' Most Southerly fence corner of BPA power sub station, bears N.32 3/4°E., 79.5'

Note - Corner lies at top of creek bank, approx. 10' south-westerly of creek, 3½' west of a southerly running fence and 8' south of a north east fence line.

Doug. County Surveyors Office - Randall W. Smith & Stephen J. Flause. Mar. 30, 1993 - C.S. File 64/43-1

North Witness Corner

Found - 2½" dia. DCSO Brass Cap on a 1½" O.D. iron pipe protruding 8" above ground marked County Surveyors Office, T27S R7W Wit. Cor. 150' south to ¼ Cor S31|S32 1960.

No Bearing Trees found.

New - A triple trunked Ash, double blazed and scribed "WC ¼S32 CSBT" on 12" dia. Northwest trunk, root crown bears S.47°E., 11.8 ft.

Most Northerly fence corner of BPA sub station, bears S.8¼°E., 94.8 ft.

BPA Power pole "RF1 11A" bears S.70½°W., 161.6 ft.

Note - Corner lies approx. 15 ft. Southwest of Southeast running creek 4 ft. from top of southerly bank.

Fd. (WC North) BC by A Silbernagel - 05/2018 - M174-28 A-B