

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32 of T26-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tony Hostetter - For: Weyerhaeuser Co. - May 2001 - C.S. File 65/37-11

Found - 1961 brass cap by DCS0 as described by BLM in 1974. 36" Fir stump OBT, & both BTs mkd. by BLM in 1974 are present.
New BTs- 10" Fir scribed "S32 ¼ BT" WEYCO tag, bears N.65°45'E., 7.4 ft. to spike placed in root collar below scribing.
12" Fir, scribed "S5 ¼ BT" WEYCO tag, bears S.4°E., 20.9 ft. to spike placed in root collar below scribing.
17" Fir, face evident (BLM tag), WEYCO tag, bears S.11°19'W., 29.8 ft. to spike placed in root collar below face.

Fd. Ok on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1990, surveyed 2001/2002 (DCS0 rec. Vol. 54 pg(s) 21010-11)

Ron Quimby - For: Weyerhaeuser - June 2017 - M173-35

Found - Brass cap per 1961 renewal
19"x6' tall hemlock stump bears N.19°E., 122.1' - healed double blaze
36" sawed fir stump bears S.58°E., 8.6' partially visible scribe
17" fir bears S.4°E., 20.9' (to spike in root collar) - healed blaze
20" fir bears S.11°W., 29.8' (to spike in root collar) - healed blaze
New BT - 16" fir bears S.65°W., 15.2' - scribed "¼ S5 BT"