

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Page 5258)

Set post, cor. secs. 8, 9, 16 and 17, from which
A W.Oak 12" dia., bears N.4¼°E., 126 lks. dist.
A W.oak 24" dia., bears N.69°W., 71 lks. dist.
A W.oak 20" dia., bears S.65°W., 90 lks. dist.
A W.Oak 22" dia., bears S.38°E., 185 lks. dist

Robert Dolan, For: Jesse Charles - June 4, 1980 - M 83-69

Set - Brass Cap
New BTs - 10" D.Fir bears N.61°18'W., 30.8 ft. scribed "T27S R7W S8 BT".
11" D.Fir bears N.14°30'E., 26.7 ft. scribed "T27S R7W S9 BT".
8" D.Fir bears S.31°02'E., 38.3 ft. scribed "T27S R7W S16 BT".
13" D.Fir bears S.14°18'W., 20.3 ft. scribed "T27S R7W S17 BT".
Sec. corner set by double proportionate measurement.

Fd BC & access. per rec. Donald Bentz, Oct. 1992 - 1993-0018
Found OK by T. Hostetter, June 2002 - M140-54

Carl Sweeden - For: Roseburg Resources Co. - Dec. 2006 - M151-78

Found - 2½" BC on 1½" GIP "1976", by LS 1076, up 0.95'
19" D.Fir BT, N.38°W., 30.3', double blaze w/scar vis., tag grown in, not listed in corner report
10" D.Fir BT @ N.61°18'W., no evidence, not found
11" now 24" D.Fir BT, N.16°E., 27.2' (N.14°30'E. 26.7'), vis. Scar, tag shows incorrect quad
8" now 19" D.Fir BT, S.33°E., 38.6' (S.31°02'E., 38.3'), vis. Double scar and tag
13" now 23" D.Fir BT, S.14°W., 21.0' (S.14°18'W., 20.3') healed, vis. scar, tag shows incorrect quad.

Fd. OK by C. Sweeden 8/2007 - M155-40
Fd. BC & 4 BTs by Ron Rice 3/2009 M158-80