

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 4; & Sec. 33 of T26-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 11 Page 4594)

Set ¼ sec. post, from which
 A B.Oak 12" dia., bears N.40°E., 25 lks. dist.
 A Laurel 20" dia., bears S.87°W., 68 lks. dist.

GL0 survey by S.C. Flint, under Contract #392 dated May 26, 1881 (DCSO records, Vol. 11 Page 4621)

Quarter post not found. Witness found. Made and set a new Hemlock post, usual length and size, from which the trees bore:
 A B.Oak 12" dia., bears N.40°E., 25 lks. dist.
 A Laurel 20" dia., bears S.89°W., 68 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy; Milo Godfrey; Clete Putnam - Dec. 1960 - C.S. File 49/79-75

Found - Orig. 20" now 34" Laurel snag, S.87°W., 44.9 ft.
 We open & find good scribing "T".
 No trace of orig. NE BT found.
Set brass cap at corner mkd: County Surveyors Office, 1960
 ¼ S33 T26S R7W
 S 4 T27S
Found 2" I.P. 5.5 ft. North at fence corner.
No trees near suitable for bearing trees.

Found OK by G. Lang, Oct. 2004 - M145-80 A & B

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2140 surveyed June/Aug. 2006- (DCSO records Vol. 57 Page(s) 22479-80)

The ¼ sec. cor. of secs. 4 and 33, on the S bdy. of the Tp., perpetuated by Byron, in 1961, from original evidence no longer in existence, monumented with an iron pipe, 1¼" dia., firmly set, projecting 13" above the ground, with brass cap (properly) mkd.
from which
 A fir, 14" dia., bears N.72¼°E., 24.3 ft., mkd. ¼ S33 BT
 A fir, 10" dia., bears S.9¾°W., 39.0 ft., mkd. ¼ S4 BT.

continued next page

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 4; & Sec. 33 of T26-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2306, Surveyed April 2010 - (DCSO records Vol. 57 Page(s) 22763-4 & Survey plat 2012-1 A&B)

The ¼ sec. cor. of secs. 4 and 33, on the S. bdy. of the Tp.. monumented with on iron post, 1/4" dia.. firmly set. projecting 5" above ground. with a brass cap (properly) mkd. from which bearing trees mkd. by Moore and Browning in 2006

 A fir. 15" dia. bears N.72¼°E., 24.3 ft. with illegible scribe marks visible on a partially healed blaze.

 A fir, 11" dia., bears S.9¾°W., 39.0 ft., with illegible scribe marks visible on a partially healed blaze.

Corner is located 1 ft. S. of a wooden fence post at the intersection of 4-strand barbed wire fences extending N., E., and W.