

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 12 Pages 5237-38)

-----  
Set 1/4 sec. post, from which  
    A B.Oak 24" dia., bears N.58°W., 26 lks. dist.  
    A B.Oak 12" dia., bears N.58°E., 26 lks. dist.

L.G. Hicks - May 1914 - M 33- 41 - C.S. 19/30 A & B - F.B. 66  
Pages 12 - 33

-----  
Fd (?) - 2" Oak Post  
    24" B.Oak, N.58°W., 28.9'.  
    18" B.Oak, N.58°E., 32.3'.  
    8" Maple, N.46°W., 7.4'.  
    12" W.Oak, N.33½°E., 6.0'.  
Set (?) - Iron pin.

Herbert L. Northcraft, For: Sheppard & Phillips - Sept. 1968  
M 33-44 & M49-52

-----  
Found - Oak stump for orig. tree, N.58°W.  
    Maple with blaze and remains of N.58°E. tree in  
    evidence.  
Reset 1/4 corner according to Hick's survey, 1914. (See M 49-52)  
Set Brass cap & scribed.  
New BTs - 12" Fir N.16½°E., 55.3 ft. mkd. 1/4 S13 T27S R7W BT  
    750  
    8" W.Oak S.32 3/4°E., 39.7 ft. mkd: 1/4 S13 T27S R7W  
    BT 750.

Don Bentz - For: Hal & Jill Anderson - March 1989 - M107-62

-----  
Found - 5/8" IR w/cap  
    22" Fir bears N.16½°E., 55.3'  
    12" W.Oak bears S.32¾°E., 39.7'  
    FD. tags & scars.  
Set (per legend) -  
    5/8"x30" IR with cap mkd: "BENTZ SURV. INC"  
(Info added 11/19/2002 DCSO)

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 10/23/2002 - C.S. File 66/34-40

-----  
Found - 5/8" iron rod with "IE" plastic cap protruding 5"  
    out of ground.  
    1968 M33-44 BC/IP N.F.  
continued next page

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" now 24" dia., D.Fir with a fully healed double blaze bears N.16½°E., 55.3 ft.  
8" B.Oak now 11" W.Oak with a fully healed single blaze bears S.31½°E., 39.7 ft. (rec. S.32¾°E., 39.7 ft) 1968  
24" B.Oak now rotted Oak remains bears N.54°W., 33.0 ft. (orig. rec. N.58°W., 17.2 ft. 1914 rec. N.58°W., 28.9 ft.)  
No evidence of orig. NE BT fd.  
8" now hollowed out rotted Maple bears N.51½°W., 8.5 ft. (Rec. N.46°W., 7.4 ft.) 1914?  
1914 NE BT not fd.  
5/8" iron rod with "IE" plastic cap bears South 23.5 ft., protrudes 4" out of ground. From this monument a 1¼" dia., square topped old rebar bears S.65°W., 0.5 ft., protrudes 2" out of ground. No BTs found for these monuments.  
New - New fence runs South with down fence running North evidence of old fence to the east, going into the south monuments.  
Compass decl. 17½°E.  
(Found I.E. iron rod set in 1989 M107-62)

Fd. OK by G.Lang - 12/2004 - 2005-0023