

TOWNSHIP 27 RANGE 07 POINT IDENTIFIER # 629360

PRIMARY CORNER DESCRIPTION NE Cor. Gov. Lot 5, Sec. 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 11/6/2002 - C.S. File 66/34-36

Note: This corner was orig. set on M33-41, by Hick in 1914. M68-63 & C.S. File 58/153-4 by Baughman mkd. new BTs in the area in 1978 & on M75-60 Miller used Baughman's corner.

**2002 DCSO corner report**

Found - 18" now 29" dia., W.Oak. We open & find good scribe marks & blaze (rec. SW 3.7 ft.) (1914) Note blaze faces N.45°E.

Depression in ground found near position of 1914  
1978 M68-63 found stone measures 12"x6"x12"  
protrudes 4" out of ground no mark found. (1914  
rec. 4"x6"x10")

From 1978 fd. stone:

7½" now 14" dir. D.Fir with a fully healed single  
blaze bears N.40°E., 7.6 ft. (1978)

9½" now 13" dia., D.Fir with a fully healed single  
blaze bears S.18°E., 34.9 ft. (1978)

From a position N.45°E. 3.7 ft from blaze of 1914 BT  
1978 fd. stone bears S.87°W., 9.0 ft.

Fence corner with fence lines running south & west  
bears N.85°W., 15.2 ft.

New - We flag up 1978 BTS & stone  
BT tag placed on 1914 BT.  
Compass decl. 17½°E