



TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION Standard ¼ sec. cor. S.32, (South)

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

42" Fir stump bears S.11½°W., 38.3 ft. with a boat spike driven in top marked "BO 1"  
Corner is 30 ft. South of logging road at edge of temporary landing.

Tony Hostetter - For: Weyerhaeuser - Feb. 2005 (added 7/31/2019) - M147-36

-----  
Found - 1961 BLM brass cap from which:  
42" Fir stump, BLM tag, spike in top, bears S.11°W., 38.3 ft.  
38" Fir stump, described by DC Surveyor has been uprooted.  
New BTs- 14" Fir, scribed "S32 ¼ BT", bears N.15°E., 10.2 to spike.  
16" Fir, scribed "S32 ¼ BT", bears S.10°E., 11.9 ft. to spike.  
BTs measured to 6" spikes placed in root collar below face.