

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5326)

Set yew post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on W face; from which
A cedar, 50" dia., bears S.55°W., 228 lks., mkd: ¼ S BT.
A fir, 74" dia., bears S.9°E., 294 lks., mkd: ¼ S BT.

Shaner Engineering - For: Hub Lumber Co. - June 24, 1974 - RM 2-63

Set - Brass cap mkd. T27S R8W WM ¼ S4 S3 1974 from which a:
74" D.Fir original BT now fire scarred stump, bears S.9°E., 194.0 ft
50" Cedar orig. BT badly burned stump with probable face, bears S.55°W., 214.0 ft. (Record, 150.5 ft.).
84" D.Fir, orig. line tree, now badly burned stump, bears South, 278.0 ft. (Record 334.0 ft.)
48" D.Fir orig. line tree now badly burned stump, bears North, 214.0 ft. (record, 194.0 ft.)
Stream, 4 lks. wide, course NW, bears south, 625.0 ft. (record, 594.0 ft)
New - 14" D.Fir, I scribed "S3 ¼ S BT" bears S.4°E., 11.9 ft.
18" D.Fir, I scribed "S4 ¼ S BT" bears N.31°W., 19.1 ft

BLM dependent resurvey by Harvey E. Wofford & John P. Farnsworth, Cadastral Surveyors under Group # 981 & 1065, surveyed May 1979/July 1981 - (DCSO records Vol. 44 Page(s) 17044-5)

The ¼ sec. cor. of secs. 3 & 4, perpetuated & recorded by Shaner, in 1974, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.
from which the remains of the orig. BTs
A burnt fir stump, 74" dia., bears S.9°E., 294 lks., no marks visible.
A burnt cedar snag, 50" dia., bears S.55°W., 324 lks., with burned blaze.
and BTs mkd. by Shaner
A fir, 16" dia., bears S.4°E., 18 lks., with healed blaze.
A fir, 20" dia., bears N.31°W., 29 lks., with healed blaze