

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36, T26-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by - A. R. and S.C.Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 11 Page(s) 4641)

-----  
Cor. to secs. 1, 2, 35 and 36, from which  
A Fir 30" dia., bears S.30°W., 11 lks. dist.  
A Fir 6" dia., bears S.20°E., 27 lks. dist.  
A Fir 36" dia., bears N.20°W., 47 lks. dist.  
A Fir 36" dia., bears N.60°E., 18 lks. dist.

Craig L. Templin - For: Weyerhaeuser Co. - March 22, 1973 - C.S. File 55/285

-----  
A 5/8" Iron rod as found by Weyco forester, Smith, located from a line crossing tag on a 10" Fir on Panther Creeek Rd.

Survey by Shaner Engineering - For: Hub Lumber Co. and Weyerhaeuser Co. - Dec. 21, 1973 - M 49-49

-----  
Found - 3/4" I.Rod (Weyerhaeuser survey, C.S. File 55/285)  
36" Fir stump, probable orig. BT, rotten and burnt, bears S.30°W., 7.3 ft.  
Probable orig. Fir BT, now mound of rotten wood, bears N.20°W., 31.0 ft.

Set Brass cap alongside Iron rod, mkd. T26S R8W S35 S36 T27S R8W S1 S1 1973".

New BTs- 14" D.Fir scribed "T26S R8W S36 BT" bears N.11°E., 16.5 ft.  
24" D.Fir scribed "T27S R8W S2 BT" bears S.41°W., 19.6 ft.  
12" D.Fir scribed "T26S R8W S35 BT" bears N.65°W., 33.3 ft.  
16" D.Fir scribed "T27S R8W S1 BT" bears S.88°E., 29.0 ft.