

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 609100

PRIMARY CORNER DESCRIPTION C C for Secs. 1 & 2 only, T28-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5783)

-----  
Set post cor. of secs. 1 and 2, from which  
A Maple 12" dia., bears S.75°W., 65 lks.  
A B.Oak 18" dia., bears S.28°E., 42 lks.

GL0 survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5278)

-----  
Intersect the C C to secs. 1 and 2, which is a post with witness trees as described by the Surveyor General.

Survey by Marvin C. Ramsey - For: J.H. Baxter & Co. - Filed Jan. 26, 1960 - C.S. File 51/65

-----  
Determined from the only extant orig. BT.:  
16" Maple bears S.75°W., 65 lks. dist., down with partial scribe marks.  
Set Iron post 3 ft. long, 1½" dia., 18" in the ground, mkd. RS 404, with mound of stone to top, from which  
38" D.Fir bears S.40°E., 87 lks. dist. mkd. T28S R8W S1 RS404 BT.  
14" D.Fir bears S.51°W., 154 lks. dist. mkd. T28S R8W S2 RS404 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; C. Putnam, crew - March 1961 - C.S. File 49/12-19

-----  
Found - Ramsey 1960 BT, SE., now stump, scribing visible.  
Ramsey 1960 BT, SW., now down, felled by loggers.  
Iron pipe at corner, not found.

Set Brass cap at cor. mkd: County Surveyors Office  
T27S R8W  
S 2 | S 1 T28S  
1961

New BTs- 32" Laurel bears N.14°E., 114.6 ft. scribed S1 & 2 T28S R8W CS BT.  
12" R.Fir bears S.2½°W., 73.2 ft. scribed S2 T28S R8W CS BT.

Fd. OK, March 1975 by V. McLind - M 55-57

(Cont. Next Page)

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 609100

PRIMARY CORNER DESCRIPTION C.C. for Secs. 1 & 2 only, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Ronald G. Geisler, LS #1988 - For: Champion International Corp. - Nov. 1985/Jan. 1986 - M 90-79  
-----  
Found - 1961 DCS0 brass cap.  
20" Fir bears S.2½°W., 73.5 ft., closed face. (1961)  
38" Fir stump bears S.40½°E., 57.42 ft. Chop marks visible on badly rotten stump. (1960 BT)  
36" Laurel bears N.14°E., 117.0 ft. (Rec. 114.6 ft.)  
No scribing visible on double face. (1961 BT)  
New BT - 9" Fir bears S.29°E., 72.6 ft. scribed T28S R8W S1 BT.

Fd. OK, Sept. 1994 by K. DeGroot - M 120-67  
Fd. Ok by Tony Hostetter - Aug. 2002 - M140-72  
Fd. Ok by Gary Smithers, June 2007 - M153-42