

TOWNSHIP 27 RANGE 08 POINT IDENTIFIER # 700160

PRIMARY CORNER DESCRIPTION N 1/16 cor. to secs. 36 & 31 of T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas County Surveyors Office - H.L. Eppstein, Co. Surveyor
June 30, 1930 - M 1-73

Cor. Set- Cedar Post 3"x3"x30"
BT Set - 12" dia. R.Fir, bears S.31°30'W., 13.6'

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - April 30, 1997 - C.S. 64/74-22

Mon. Fd.- Fence corner post at the intersection of a south
and west running fence lines (not of record)
Fence is old and of the same condition and
type of fence found at corner locations in
near area.

Cedar post set per M1-73 not found.

Accessories Fd.-
12" R.Fir now 12" dia. 3' high rotted D.Fir, with
axe marks and rotted blaze. (no scribing
found), bears S.31½°W., 13.6' from plumb
position of fence corner post. (agrees with
rec.) 1930 DCSO

20" dia. Cedar, with a rusted forrest service
location poster marked T27S R8W with a nail
indicating the N 1/16 cor. on east side of
sec. 36 other marks are unreadable. Cedar
tree and tag are approx. west 5' of fence
corner. Source unknown (looks old)

Mon. Set - No monument set as corner falls at a point of an
existing fence corner.

New Accessories -
9" dia. W.Fir, double blazed and scribed "N 1/16
S31 CS BT", bears S.51°E., 14.6'.
10" dia. Madrone, double blazed and scribed "N
1/16 S36 CS BT", bears S.4°W., 28.7'.
7" dia. Madrone, double blazed and scribed "N
1/16 S31 CS BT", bears N.1½°E., 18'.