

TOWNSHIP 28 RANGE 01 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Cor. Secs 4, 5, 8, & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 resurvey by Homer D. Angell, Deputy Surveyor, under contract #746, dated May 5, 1902 - (DCSO records Vol. 13 Page(s) 5408)

Set a basalt stone 15x10x6", 10" in the ground for cor. of secs. 4, 5, 8, & 9 mkd with 5 notches on S & 4 notches on E edges, from which

- A dogwood, 12" dia., bears N.55°E., 15 lks., mkd: T28S R1W S4 BT.
- A pine, 12" dia. bears S.79°E., 35 lks mkd: T28S R1W S9 BT
- A dogwood, 10" dia., bears S.10°W., 54 lks., mkd: T28S R1W S8 BT.
- A fir, 14" dia. bears N.14°E., 14 lks. mkd: T28S R1W S5 BT

Post card from Jim Talburt, dated 12/31/1970 - C.S. 54/94-102

Actual corner not found.
Found - 22" D.Fir with old blaze visible. Corner is approximately 200' SE of end of forest road #2793 in Sec. 5.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 2/28/1972 - C.S. File 54/94-102

Searched for - not found.
Fd. erratic blazed line & a 22" Fir with an injury - no trace of orig. BTs. Covered an area approx. 500'x 500' - Rd. #2793 does not end now - I would consider this corner. NF.
