

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 13 Page(s) 5512)

-----  
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4     S 14  
         S 23

1923

from which

A fir, 22" dia., bears N.20°E., 45 lks., mkd: 1/4 S14 BT.

A hemlock, 10" dia., bears S.20°W., 28 lks., mkd: 1/4 S23 BT

-----  
Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1968 - C.S. File 54/26-10

-----  
Found - 1923 GLO Brass cap, properly mkd.  
22" now 24" W.Fir alive N.20°E., 29.7 ft. shows good scar. We do not open.

10" now 16" hemlock alive broken top about 40 ft up, S.20°W. 18.5 ft shows good scar. We do not open

New BTs- 8" hemlock S.67°W., 9.8 ft. mkd: "1/4 S23 CS BT"

10" D.Fir N.23°W., 6.7 ft. mkd: "1/4 S14 CS BT"

This corner lies on moderate W. slope approx. 400 ft. W of USFS Road RD. 2834, line tag on 17" Hemlock on E side of road

-----  
Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - Sept. 6, 1988 - C.S. File 62/55-6

-----  
Found - 1923 GLO 2 1/2" disk on a 1" O.D. IP protruding 12" above ground and leaning 8" west of plumb.

22" now 22" dia. 14" high rotted fir stump with a fully healed lower blaze, blaze opened and illegible scribing found, bears N.20°E., 29.7 ft. (agrees with record) Original BT.

10" now 13" dia. down hemlock with a fully healed blaze, bears S.20°W., 18.5 ft. to center of remaining root crown. Orig. BT.

8" Hemlock now an 8" dia. fallen southwesterly and broken, dead hemlock with a partially healed single blaze with scribing "1/4" S23 CS BT visible, Has stump hole bearing S.67°W., 9.8 ft. (Agrees with record)

A 10" D.Fir now measuring 9" DBH and now a dead 35 ft. tall snag with the scribing "1/4 S14 CS BT visible on a partially healed single blaze bears N.23°W., 6.7 ft. (as per rec.) to center of trunk above blaze and N.16 1/2°W., 6.7 ft. to center of root crown.

continued next page

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set - Monument is straightened to plumb position and is now firmly set protruding 10" above ground.

New BTs- 6" DBH Hemlock double blazed and scribed "¼ S23 CS BT" bears S.71½°W., 88.5 ft.  
6" DBH Hemlock double blazed and scribed "¼ S23 CS BT" bears S.06°W., 113.4 ft.

New BOs- A boat spike stamped BO 1 set through a bearing tree tag at the center of a 48" dia. 18" high D.Fir stump bears N.82½°E., 19.6 ft. distant.  
A boat spike stamped BO 2 set through a bearing tree tag at the center of a 24" dia. 1 ft. high D.Fir stump bears N.32½°W., 62.9 ft. distant.

Monument is in a clearcut and approx. 400 ft. west from a line crossing fir tag on a G.Fir at the east edge of USFS Rd. 780.