

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 604100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only, T29-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6241)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 cor. of sec. 1 only, with brass cap mkd:

1/4 S1
1917

from which

A Fir 18" dia., bears S.24°15'E., 33 lks. dist. mkd. 1/4 S1
BT.

A Fir 10" dia., bears S.51°30'W., 8 lks. dist. mkd. 1/4 S1
BT.

Fd. and used in GLO resurvey by Fred Mensch, under Special Instructions dated June 7, 1922 - (DCSO records Vol. 13 Page(s) 5491)

Douglas Co. Surveyors Office - Dennis Gaylord, U.S.F.S. (Deputized by the County) Wit: Roland Simshauser - April 20, 1978 - C.S. File 59/46-43

Found - 1917 US GLO brass cap on a 1" I.P., 14" above ground and solidly set in place. I ADD "T29S R2W" to brass cap below the "1/4 S1".

21" D.Fir bears S.24°15'E., 22.4 ft. (Rec. 21.78 ft.) has a healed scar.

13" D.Fir bears S.51°30'W., 5.6 ft. (Rec. 5.28 ft.) Has a healed scar.

Placed County BT signs on both.

No new monument or accessories.