

TOWNSHIP 28 RANGE 02 POINT IDENTIFIER # 700600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 12 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 13 Page(s) 5488-89)

Set an Iron post 3 ft. long, 2' dia., 27" in the ground for cor. of secs. 1 & 12 only, with brass cap mkd.

T28S		T28S
<u>S 1</u>		R1W
S12		
R2W		S7
1923		

from which

A Fir 36" dia., bears S.45°W., 24 lks. dist. mkd. T28S R2W S12 BT.

A Fir 36" dia., bears N.78°W., 11 lks. dist. mkd. T28S R2W S1 BT.

Douglas Co. Surveyors Office - Jim Cook; M. Lenora Ladig, crew - Aug. 2, 1976 - C.S. File 59/18-12

Found - 1923 GLO brass cap properly stamped.

A 36" now 45" Fir bears S.45°W., 16.0 ft. Tree is alive with well healed blaze.

A 36" now 42" Fir bears N.78°W., 7.4 ft. Tree is alive with well healed blaze.

Corner OK. Did Not Renew. Cor. lies approx. 200 ft. South of T28-1 West ¼ cor. sec. 7. Also lies 10 ft. South of Rd. #274.