

PRIMARY CORNER DESCRIPTION Sec Cor for 1 & 12 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882 - (DCSO records Vol. 13 Page(s) 5423-24)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 1, 6, 7 and 12, and marked T28S S6 on NE.; R2W S7 on SE.; R3W S12 on SW. and S1 on NW. faces, with 1 notch on N. and 5 notches on S. edges, from which
A Fir 24" dia., bears N.25°E., 39 lks. dist. mkd. T28S R2W S6 BT.
A Fir 20" dia., bears S.55°E., 20 lks. dist. mkd. T28S R2W S7 BT.
A Fir 30" dia., bears S.70°W., 46 lks. dist. mkd. T28S R3W S12 BT.
A Fir 30" dia., bears N.5°W., 58 lks. dist. mkd. T28S R3W S1 BT.

GLO survey by William N. Gibb, Deputy Surveyor, under Contract #783, dated Dec. 3, 1908 - (DCSO records Vol. 13 Page(s) 5478)

(after established cor. for 6 & 7) "I destroy markings on other corner and bearing trees referring to secs. 6 & 7."

Thomas E. Shrum, Jr. - For: U.S. Plywood Corp. - June 1962 - M 25-7

Found - 41" Fir N.3°W., 40.0 ft.
39" Fir N.28°E., 28.0 ft.
24" Fir S.51°E., 14.0ft.
36" Fir stump S.87½°W., 31.2 ft.
Set 2½" aluminum cap and 3 BTs:
11" W.Fir S.14½°W., 18.2 ft.
13" W.Fir S.83°E., 17 ft.
11" W.Fir N.15°W., 46.9 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - John Powell & Wm. Stoffel, crew - Aug. 1962 - C.S. File 52/126-37

Found - 3/4" Iron pipe with alum. cap at cor. set by Shrum mkd. U.S.P.C. Prop. Cor. R3W S1 S12; S7 R2W T28S 1961.
Orig. 30" now 36" Fir snag, S.70°E., 30.4 ft., no scribing found.
Orig. 30" now 40" Fir N.5°W., 38.3 ft., shows good bark scribing.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 1 & 12 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>1961 BT, 7" W.Fir N.15½°W., 46.9 ft. scribed T28S. 1961 BT, 12" W.Fir S.16°W., 18.5 ft., scribed T28S R3W S12 BT. 1961 BT, 13" W.Fir S.84°E., 16.6 ft. scribed T28S R2W S7 BT.</p>
<p>Ronald A. Quimby - For: U.S. Forest Service - March 1980 - M 79-37 ----- Found - 1" Iron pipe with alum. cap mkd. U.S.P.C. Prop. Cor. T28S R3W S1 S12 S7 R2W RE #4287. 14" Hemlock stump S.16°W., 18.5 ft. 16" D.Fir stump S.84°W., 16.6 ft. visible scribes. Set fiberglass post and signs 4.0 ft. North. New BTs- 14" Pine N.86°W., 184.0 ft. "S1 T28S R3W BT" 8" Hemlock N.56°W., 152.0 ft. "S1 T28S R3W BT". Brass washers RLS 1005 in BT faces.</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - July 15, 2013 - C.S. File 67/38-39 ----- Found - 1962 2½" dia., alum. cap (properly mkd) on a 1" O.D. iron pipe protruding 8" above ground. A fir 24" dia., now a 40" dia., 4 ft. tall fir stump with a previously opened blaze (scribing destroyed in 1908); bears N.25°E., 27.7 ft. (bearing agrees with orig., orig. distance of 25.7 ft. is good to 1882 face) OBT A fir 20" dia., now a 25" dia., 2½ ft. tall fir stump with a previously opened and partly rehealed but now rotted face (scribing destroyed in 1908) bears S.55°E., 14.1 ft. (bearing agrees with orig., orig. distance of 13.2 is good to 1882 face) OBT A fir 30" dia., now a 36" dia, 2 ft. fir stump with no blaze of scribing evidence; bears S.71½°W., 30.4 ft. (rec. S.70°W., 30.4 ft.) OBT A fir 30" dia., now a 40" dia., 2½ ft. tall fir stump no longer showing bark scribing (described in 1962 DCSO renewal) bears N.5°W., 39.4 ft. (bearing agrees with orig. dist. of 38.3 ft. is good to 1882 face) OBT An 11" W.Fir now a rotted low base of a fir stump, bears S.14½°W., 18.2 ft. (as per rec.) 1962 A 13" W.Fir now a 16" 1½ ft. tall fir stump with remnants of a rotted blaze showing no scribing; bears S.81°E., 17.0 ft. (rec. S.83°E. 17 ft) 1962 continued next page</p>

PRIMARY CORNER DESCRIPTION Sec Cor for 1 & 12 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

An 11" W.Fir now a 10" dia., 1 ft. tall mostly rotted away fir stump with no marks remaining; bears N.15°W., 46.9 ft. (as per record) 1962

A 14" pine now a 34" dia., Sugar Pine with a fully healed single blaze (and a 1980 alum. BT tag); bears S.86½°W., 181.7 ft. (Rec. N.86°W., 184.0 ft.) 1980

The NW hemlock position now falls under a pile of road waste.

New - A 15" dia., I.Cedar scribed "T28S R2W S7 CS" "BT" on a double blaze; bears S.37°E., 12.7 ft.

A 14" dia., D.Fir scribed "T28S R3W S12 CS" "BT" on a double blaze; bears S.67°W., 24.0 ft.

A 13" dia., W.Fir scribed "T28S R3W S1 CS" "BT" on a double blaze; bears N.42½°W., 30.0 ft.

Also (of unknown origin) an orange carsonite post protruding 4 ft. above ground with a monument location sign bears S.75°W., 4 ft. dist.

Note - Monument near bottom of a moderately steep westerly slope in a 30+ year old reprod. forest of D.Fir & W.Fir with some maple & pine.

Monument is approx. 70 ft. East from an old graveled forest road.

Compass decl. 15½°E.