

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 037020

PRIMARY CORNER DESCRIPTION SE Cor. Ledgerwood DLC #37

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original survey by J.A. Burnett, under Contract dated Jan. 8, 1857</p> <p>-----</p> <p>Set post, from which A W.Oak 10" dia., bears N.15°W., 143 lks. Raised mound with trench as per instructions.</p>
<p>F.C. Frear, D.C.S. - Wit: C.J. Ingram; M. Adams - Dec. 11, 12, 1918 - Vol. 3 Pg. 45; "Old" cor. book, pg. 103</p> <p>-----</p> <p>Renewed from old bearing tree. Set in 3/4" x 36" Galv. Iron Pipe, from which Old Gov't W.Oak, remarked, still stands.</p>
<p>Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey - July 6, 1961 - C.S. File 49/67-8</p> <p>-----</p> <p>Found - Orig. 10" now 28" W.Oak N.15°W., 94.4 ft. We open and find Frear's scribing "T" We do not find 3/4" I.P. set by Frear. Set brass cap at cor. mkd: County Surveyor's Office, 1961 S.E. Cor. DLC 37 T28S R4W New BTs -12" W.oak bears N.41°W., 76.4 ft. scribed SE DLC 37 CS BT. 10" W.Oak bears N.65°W., 80.9 ft. scribed SE DLC 37 CS BT.</p>
<p>Corner Fd. OK, by Lynn M. Roseberry, BLM resurvey in 1967 (DCSO records, Vol. 34 Pages 14200-01)</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/14/2000 - C.S. File 66/14-27</p> <p>-----</p> <p>Found - 1961 DCSO BC/IP, protrudes 15" above ground. 10" now 16" dia., W.Oak with a fully healed double blaze, bears N.65°W., 80.9 ft. 1961 12" now 18" dia., W.Oak with a fully healed double blaze, bears N.41°W., 76.4 ft. 1961 10" now 33" dia., dead W.Oak with a previously opened rotted blaze, bears N.15°W., 94.4 ft. OBT New BT - 18" dia., I.Cedar double blazed & scribed "SE DLC 37 CS BT" bears S.46½°W., 14.3 ft. (Note: BT out of DLC) Fence corner with fence line running West & North bears West 8 ft.</p>
<p> </p>