

PRIMARY CORNER DESCRIPTION 1/4 Cor. to Sec's. 30 & 31.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13, Pg. 5637)

Set post for 1/4 sec. cor. & built mound etc. as per instructions.
No bearing trees convenient.

B.A. Shaner for: Paul B. Hult Lbr. Co.- July 1964, M22-57 & C.S. File No. 51/296.

Found - Nothing.
Set - 5/8" Iron Rod by proportion.
New BTs - 10" D.Fir, bears S.9°E., 139.0' mkd: 1/4 S S31 BT.
8" I.Cedar, bears N.81°W., 171.0' mkd: 1/4 S S30 BT.

Kris DeGroot - For: Roseburg Resources Co. - 2/2007 - M 152-26

Found - 5/8" iron rod by Shaner in 1964 per M22-57, firmly set, projecting 2" above ground in an east-west fence line

Set - 2" alum. cap on the M22-57 iron rod, stamped:
T28S R4W
1/4 S 30
S 31
PLS 1941

From which bearing trees by Shaner in 1964:

A 18" D.Fir snag bears S.9°E., 139.0 ft w/healed blaze
A 19" Cedar bears N.81°W., 171.0 ft w/healed blaze.

New BT - A 12" cedar bears S.32°E., 119.8 ft scribed "1/4 S31 BT.

New RMs - A 5/8"x30" iron rod bears S.88°58'35"E., 83.20 ft
A 5/8"x30" iron rod bears N.1°01'25"E., 25.00 ft.