

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. secs. 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5642)

-----  
Set Fir post for ¼ sec. cor., from which  
A Fir 10" dia., bears N.15°E., 22 lks.  
A Fir 14" dia., bears S.42°W., 60 lks.

BLM resurvey by G. Steven Popken, under Group #837 - Survey, June/July 1974 (DCSO records, Vol. 37 Page 15371)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd:  
T 28 S R 4 W  
1/4  
S 7 | S 8  
1974

from which  
A Fir 18" dia., bears S.46°E., 60 lks. dist., mkd.  
1/4 S8 BT.  
A Fir 15" dia., bears S.19°W., 39 lks. dist., mkd.  
1/4 S7 BT.  
Corner is located on spur, slopes N.85°W.

Fd. OK, July 1991, Glenn Baughman, M 113-49

David Edwards - For: Seneca Jones Tbr Co - 4/2010 - M 160-56

-----  
Found - Brass cap  
20" Fir bears S.46°E., 39.6'  
17" Fir bears S.19°W., 25.7'  
Both w/healed blaze.