

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. sec. 32; & S. 5 of T29-4.

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, Contract # 44 dated May 30, 1854
(DCSO records Volume 13, Pg. 5607)

Set 1/4 sec. post at proper distance from which:
A Dogwood, 4" dia., bears N.5°W., 12 lks. dist.
A Yew, 4" dia., bears S.43°W., 13 lks. dist.

South boundary of T.28-4, surveyed by W.H. Byars, Contract
376 dated Jan. 22, 1881. (DCSO records Vol. 13 Pg. 5613)

Set a yew post for 1/4 sec. cor. from which:
A Fir, 8" dia. bears N.12°W., 43 lks. dist.
A W.Fir, 8" dia. bears S.45°W., 10 lks. dist.
Note: Per note in Byars 1881 survey "In the execution of this
work I found that the old line established for the S bdy of
this Township was glaringly at fault..." Byars set his own
corners. See CS 63/166 BLM opinion file T28-4 (added 4/7/2010)

Frank Cain Co. Surveyor, witnesses, F.J. Cole, J.T. Black
Wm. Berdine. Surveyed for W.H. Lawrance. May 1915.
(DCSO records Vol. 2 pages 222-226 & 231-232, also FB no.
34, pages 14-24).

Renew corner from stumps of orig. Wit. trees. Set charred
post from which:
A R.Fir, 10" dia. bears S.39°05'E., 56 lks. dist.
A R.Fir, 5" dia. bears S.28°W., 60 lks. dist.

G.J. Wenderoth Deputy Co. Surveyor, (DCSO records M28-78)
Nov. 1946.

Renewed Cor. from old BTs.
Set - 1¼" iron pipe for corner.
New BTs - A Fir, 14" dia. bears S.2°10'W., 10.7 ft.
A Fir, 10" dia. bears S.70°36'W., 24.8 ft.

James W. Byron, Deputy Co. Surveyor - April-May 1957
C.S. File 47/180.

Found - 1¼" I.P. at corner bent over by cat. Replaced
with brass cap. The 14" Fir, S. 2°10'W., in good
condition and shows good face-I do not open.
The 10" Fir, S.70°36'W., down. Both BTs check
for bearing & Distance.
Lower section of charred post as set by Cole, same
location as 1¼" I.P.

(Cont. Next Page)

