

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 25 and 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5616)

Set Yew post for ¼ sec. cor., from which
A Fir 24" dia., bears S.60°E., 35 lks.
A Fir 36" dia., bears S.35°W., 33 lks.

John H. Markham, Jr. for: S.Y.M. Logging Co. Wit: L.B. Campbell - Feb. 17, 1958 - C.S. File 42/330

As determined by O.B.T's
40" Fir bears S.60°E., 23.1 ft. found scribed & remarked (bark)
45" Fir windfall bears S.35°W., 21.8 ft.
At cor. point, set 1" x 30" I. Pipe, from which
8" W.Fir bears S.60°W., 13.8 ft. mkd. ¼ S26 BT.
7" W.Fir bears N.29°W., 16.6 ft. mkd. ¼ S26 BT.
11" W.Fir bears N.9°E., 18.4 ft. mkd. ¼ S25 BT.
Creek bears West, 130.0 ft.
Road bears West 330.0 ft.

BLM resurvey by Zirpel and Glenn, under Special Instructions dated August 29, 1957 (DCSO records, Vol. 29 pages 12224-25)

Found ¼ cor. as perpetuated and recorded by Markham in 1958, at record bearing and distance from orig. SE bearing tree, monumented with an I.P. 1" dia., firmly set, 6" above ground. from which the original bearing tree:

A Fir 42" dia., bears S.60°E., 35 lks. dist., with scribe marks ¼ S BT visible on a bark blaze. Rescribed ¼ S BT on a bark blaze by markham in 1958.

and substantiated by:

A turnout hole, bears S.35°W., 33 lks. dist.

bearing trees added by J.H. Markham in 1958:

A W.Fir 11" dia., bears N.9°E., 27½ lks. dist. mkd. ¼S25BT

A W.Fir 8" dia., bears S.60°W., 21 lks. mkd. ¼ S26 BT.

A W.Fir 7" dia., bears N.29°W., 25 lks. mkd. ¼ S26 BT.

At the corner point

Set a iron post, 28 ins. long, 2½ ins. diam., 26 ins. in the ground, with brass cap mkd: T28S R4W

¼
S26|S25
1958

Reset Iron pipe alongside iron post.

Found OK by. R. Rice, Nov. 2002 - M141-27