

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 35 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - A.R. Flint & L.L. Williams, under Contract #151 dated May 23, 1871 (DCSO records, Vol. 13 Page 5683)

Set post to 1/4 sec. corner, from which
A B.Oak 8" dia., bears N.75°W., 225 lks. dist.
Stone one foot above ground marked with an X bears
N.30°E., 33 lks. dist.

Doug. County Surveyors Office - James Byron, Deputy - Dale McFarland; J. Powell - Dec. 1961 - C.S. File 49/64-50

Found - Orig. 8" now 16" B.Oak N.75°W., 148.5 ft.,
previously opened, shows good scribing "BT".
Rock to NE not found.

Note: Compass needle at corner seems to be about 5° in error but OK at BT. Bearings to new BTs are as read to corner.

Set Brass cap mkd: County Surveyor's Office, 1961

1/4 S35 | S36 T28S R5W

New BTs -9" R.Fir S.54°W., 105.7 ft. scribed 1/4 S35 CS BT.
30" R.Fir N.23 1/2°E., 64.0 ft. scribed 1/4 S36 CS BT.
(This BT is at fence corner.)

Found OK, William Ruppert, Jan/March 1983, M 93-68

1961 Brass cap, orig. BT and Byron's BTs found OK by, Bureau of Land Management resurvey by Peterson & Bedell, under Group #1425 - Survey April 1988-April 1990 (DCSO records, Vol. 49 Page 18696)

(The corner is located at the corner of barbed wire fences extending W. and S.)

Fd. BC 4/2022 - Bart Heichel - M180-80