

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, and L.L. Williams Under Contract #151, dated May 23, 1871 (DCSO records Volume 13 Pages 5685-86)

Set post to corner of secs. 13, 14, 23 and 24, from which
A W.Oak 8" dia., bears N.80°W., 17 lks. dist.
A Fir 48" dia., bears N.19°E., 47 lks. dist.
A Fir 24" dia., bears S.30°E., 100 lks. dist.
A W.Oak 6" dia., bears S.4°W., 81 lks. dist.
Summit of Dodson Mt. S.15°E.

Claude Kerr, Logging Engineer - July 1950 (Found no record source)

Found only one remaining BT in good condition. This BT is the 48" D.Fir bearing N.19°E., for 47 lks. from corner. Scribe on bark reads S.13 T28S R5W. I reset this corner from the BT, using a 4" x 4" Incense Cedar post and marking S13, S14, S23, and S24 with crayon on proper faces of the post.

Doug. County Surveyors Office - James Byron, Deputy - John Powell; Dale McFarland - Dec. 1961 - C.S. file 49/64-41

Found - Orig. 48" now 48" Fir snag, N.19°E., 31.0 ft., shows good bark scribing "BT"
We also find remains of SW and NW BTs.
SE BT, now down.
We find squared stake down at corner.
Set Brass cap at cor. mkd. County Surveyor's S14|S13
Office, 1961 S23|S24
New BTs -9" Cedar bears S.89°E., 17.6 ft. scribed S24 CS BT.
26" R.Fir bears N.88°E., 55.6 ft. scribed S13 T28S R5W CS BT.
14" R.Fir bears N.62°W., 36.7 ft. scribed S14 T28S R5W CS BT.
8" Cedar bears S.61°W., 28.3 ft. scribed S23 CS BT.

Found OK, August 1990, M 110-57

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda - 7/21/2008 - C.S. File 67/25-64

Found - IP BC fd. projecting 26" above ground leaning & loose with flanges still well embedded in remains of stone mound. BC is 2½" dia., & is (properly) marked.
continued next page

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

24" Fir OBT now roothole, measured to deepest point of hole bears S.30°E., 66.0 ft. (as per rec.)
48" Fir OBT now roothole of burnt snag with root still intact in ground, bears N.19°E., 313.0 ft. (as per rec)
26" R.Fir now 26" dia., 20" tall stump with scribing "BT" visible bears N.83½°E., 53.7 ft. (Rec. N.88°E., 55.6 ft.)
9" Cedar now 9" dia., burnt & rotten stump 1.5 ft. tall, no marks, bears N.86½°E., 16.6 ft. (rec. S.89°E., 17.6 ft.)
New - Fd. plumb position of mon. referenced hole deepened & mon. reset at ref. position now prot 8" above ground.
4" dia., D.Fir bears N.19°E., 16.6 ft. scribed "X CS BT" on a high-low blaze.
4" dia., D.Fir bears S.6°E., 18.0 ft. scribed "X CS BT" on a high-low blaze.
Note - Monument is East of private access rd. (see sketch) & is approx. 100 ft. east from top of N-S running ridge on a steep east facing slope.
Compass decl. 16¼°E.

Kristian DeGroot - For: Jesse Family LLC - Oct 2012 - M157-64

LAT: 43°07'38.62374" N. LONG: 123°14'44.76284" W.
Found a 1961 DCSO BCIP by J. Byron per C.S. 49/64, reset in 2008 by DCSO with accessories per renewal C.S. 67/25-64.