

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5732)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Y.Oak 14" dia., bears N.17½°W., 106 lks. dist. A Y.Oak 20" dia., bears N.67°E., 82 lks. dist.</p>
<p>Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; S.A. Bilow - Nov. 1958 - C.S. File 49/50-22</p> <p>-----</p> <p>Found - Orig. 20" now 30" B.Oak N.67°E., 70.0 ft. I open & find good scribing "S". Find stump hole that checks bearing and distance for orig. NW BT. Set Brass cap at cor. mkd: ¼ S31 S32 T28S R6W County Surveyors Office, 1958 New BTs- 14" R.Fir bears N.25°E., 50.9 ft. scribed ¼ S32 CSBT 15" R.Fir bears N.29°W., 40.9 ft. scribed ¼ S31 CSBT</p>
<p>Fd. 1958 DCSO brass cap and 3 BTs.- BLM resurvey by Wayne Rogers, Group #1351, Survey 1987 (DCSO records, Vol. 48 Page 18439)</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/10/2001 - C.S. File 66/19-6</p> <p>-----</p> <p>Found - 1958 DCSO brass cap/iron pipe, protrudes 12" out of ground. BC/IP is at a fence corner with fence line running south & east. 20" now 27" dia. 12 ft. tall rotted Oak snag, previously opened unhealed blaze, scribing visible "S" bears N.67°E., 54.1 ft. (agrees w/orig. rec.) OBT 14" now 25" dia., D.Fir with a fully healed single blaze bears N.25°E. 50.9 ft. (agrees w/1958 rec.) 15" now 24" dia., D.Fir with a fully healed single blaze bears N.29¼°W., 40.9 ft. (agrees w/1987 BLM rec.) 1958 New - 11" dia., D.Fir double blazed & scribed "¼ S31 CS BT" bears S.60°W., 25.0 ft. 7" dia., Madrone single blazed & scribed "¼ S32 CS BT" bears S.12½°E., 26.5 ft. Compass decl. 17 ¾°E.</p>
<p>Fd. BC & 5 BTs by Carl Sweeden, 1/2013 - M164-58</p>
<p> </p>