

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2 of T29-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5698)

Set post cor. to secs. 1, 2, 35 and 36, from which
A Y.Oak 15" dia., bears S.21°W., 126 lks. dist.
A W.Oak 10" dia., bears S.4°E., 75 lks. dist.
A W.Oak 12" dia., bears N.85½°E., 98 lks. dist.
A Y.Oak 24" dia., bears N.25 3/4°W., 342 lks. dist.

Doug. County Surveyors Office - James Byron, Deputy; Dale McFarland; John Powell - Dec. 1961 - C.S. File 49/139-5

Found - Orig. 12" now 18" W.Oak N.85½°E., 64.7 ft. We open and found scribing.
Orig. 24" now 40" B.Oak N.25 3/4°W., 225.7 ft. shows scar.
Orig. SE BT not found.
Orig. 15" now 24" B.Oak S.21°W., 83.2 ft. shows scar. I do not open.
Set Brass cap at cor. mkd: County Surveyors S35|S36 T28S R6W
Office, 1961 S 2|S 1 T29S
New BTs - Rescribe orig. 12" now 18" W.Oak, N.85½°E., 64.7 ft. scribed S36 T28S R6W CS BT.
13" B.Oak bears N.2½°W., 59.3 ft. scribed S35 T28S R6W CS BT.
Rescribe orig. 15" now 24" B.Oak S.21°W., 83.2 ft. S2 T29S R6W CS BT.
10" Tr. Laurel bears S.1½°E., 30.0 ft. scribed S1 CS BT.

John H. Markham, Jr. - Sept. 1968 - C.S. File 51/292

At Corner point, found I-5 Hwy fill. Brass cap buried, from which:
18" W.Oak N.85°E., 64.7 ft. (O.B.T.)
13" B.Oak N.2°W., 59.3 ft. (O.B.T.)
All other trees missing.
6" steel sign post set in concrete reads: Portland 187 - Roseburg 10, bears S.60°30'W., 102.0 ft. slope distance.
East end Freeway culvert 48" dia., bears S.30°E., 135.5 ft. slope distance.

(Cont. Next Page)

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. 35 & 36; 1 & 2 of T 29-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Doug. County Surveyors Office - Larry E. Monrean, Deputy -
Pete Earle - Oct. 23, 1973 - C.S. File 56/39-8

Found - 13" B.Oak N.3°W., 59.3 ft. scribed S35 T28S R6W CSBT
18" now 22" W.Oak N.85½°E., 64.7 ft. scribed S36
T28S R6W CS BT.
6" Steel sign post set in concrete bears S.62°W.
East end of culvert 48" dia., bears S.31°E.
Set brass cap at sec. cor. mkd: County Surveyors T28S R6W
Office S 35 | S36
1973 S 2 | S 1
T29S R6W

New BTs - 18" W.Oak bears S.34½°E., 196.4 ft. scribed T29S
R6W S1 CS BT. Following are slope distances
and angles taken to BT: 82' @ 19°=77.5 ft.
100' @ 4°30'=99.7 ft.
19.2' level = 19.2
196.4 ft.

Fd. OK OSHD - May 1986, C.S. 63/9-7 - Replaced steel sign post
FD Ok by Mark Heimbürger, May. 1996 - M 123-70
Found OK by R.Quimby, July 1997 - Subd. Plat Vol. 19 Pg. 25

DCSO-GIS Corner visitation - 7/12/2004 - Typed: 2/1/2011 -
C.S. File 67/33-1

Monument - BC/IP - 1.25"
Comment - OK

Fd. ok by R. Brown, 6/2006-10/2007 - RM 4-15A&B