

PRIMARY CORNER DESCRIPTION Sec. cor. for 7, 8, 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 14 Page 5778)

-----

Set a post, cor. of secs.7,8, 17 and 18, from which

- A B.Oak 8" dia., bears S.87°W., 140 lks. dist.
- A B.Oak 10" dia., bears S.75°E., 135 lks. dist.
- A B.Oak 6" dia., bears N.82°E., 57 lks. dist.
- A B.Oak 12" dia., bears N.47°W., 62 lks. dist.

Arthur Boyer, March 8, 1957 - M 4-74

-----

This corner has been lost or obliterated. Point for corner located by double proportional measurement.

Set 3/4" iron pipe at point for corner, from which

- 24" Fir N.77°E., 6 ft. mkd. S8 T28S R7W, 1581 BT.
- 8" Laurel S.15°E., 9.0 ft. mkd. S17 BT.
- 18" Fir N.83°W., 11 ft. bark blazed, S7 BT.
- 10" Fir S.60°W., 6.3 ft. bark blazed, S18 BT.

BLM dependent resurvey by Bryan S. Seibold, & Robert J. Chappel, Cadastral Surveyor, under Group #1585, surveyed May 1991/May 1994 - (DCSO records Vol. 52 Page(s) 20016-7)

-----

The cor. of secs. 7, 8, 17 & 18, reestablished by Boyer, in 1957, and is accepted as the corner; monumented with an iron pipe, 3/4" diam., firmly set, projecting 12" above ground, from which the remains of the bearing trees mkd. by Boyer:

- A roothole, bears N.77°E., 9 lks., with uprooted 18" diam. fir alongside.
- A madrone, 17" diam., bears S.13½°E., 14 lks., with healed blaze.
- A roothole, bears S.60°W., 9½ lks., with decayed uprooted 10" diam. fir snag alongside, no marks visible on a bark blaze.
- A fir, 17" diam., bears N.86°W., 16½ lks., with scribe marks S7 BT visible on a bark blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" diam., 24" in the ground, with brass cap mkd.

T28S	R7W
<u>S7</u>	<u>S8</u>
S18	S17
1991	

and new bearing trees

- A fir, 8" diam. bears N.50°E., 41 lks. mkd. T28S R7W S8 BT
- A cedar, 11" diam., bears S.38°W., 43 lks., mkd. T28S R7W S18 BT.

Deposit a white "DEEP-1" magnetic marker at the base and the iron pipe alongside the stainless steel post.