

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32, & 33

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 14 Page 5768)

Set a post, cor. of secs. 28, 29, 32 and 33, from which
A W.Oak 24" dia., bears S.80°E., 235 lks. dist.
A B.Oak 8" dia., bears N.75°W., 236 lks. dist.
Made a trench, no other trees in a reasonable distance.

Bowker -Wit: P. D. Wolford - March 19, 1926 - C.S. File 3/39
Vol. 3 Page 255

No original trees. A stake is in place which Mr. Sprague says is the Section corner. Fir trees near this stake blazed but no scribe marks visible. Marked new trees as follows:
Red Fir 16" dia., bears N.54°E., 47 ft.
R. Fir 14" dia., bears S.55°W., 31.2 ft.
Fir 12" dia., bears N.10°W., 13.3 ft.
Fir 24" dia., bears S.10½°E., 31.0 ft.

Doug. County Surveyors Office - James Byron, Deputy - Ray Irving; John Fee - May 5, 1955 - C.S. File 46/130

Found - R.Fir 16" stump only, N.54°E., 47.0 ft.
12" R.Fir, N.10°E., recorded N.10°W., 13.3 ft.
Also found 24" R.Fir stump, S.10½°E., 31.0 ft.
The NE and NW have scribing visible.
Set brass cap at cor. mkd: $\frac{29}{32} \frac{28}{33}$ T28S R7W County Surveyor's Office, 1955
Blazed and scribed:
12" R.Fir N.25°W., 4.6 ft. mkd. S29 CS BT.
16" Fir S.46½°W., 53.3 ft., S32 CS BT.
20" Fir N.86°E., 14.1 ft. mkd. S28 CS BT.

Doug. County Surveyors Office - Vernon Tracy, Deputy - Jack Heritage; V. Perron - Sept. 30, 1968 - C.S. File 52/79

Found - Co. Surv. B.C. 5.0 ft. East of fence cor. East-West and South.
No trace of SW BT.
12" now 18" Fir, N.25°W., 4.6 ft. shows good scar.
Do not open.
20" Fir N.86°E., 14.1 ft. now stump.
New BT - 4" B.Oak bears S.35½°W., 15.5 ft. mkd. S32 T28S R7W CS BT.

Continued on next page.

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor. Secs. 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 10/12/1993 - C.S. File 64/47-2

Found -

2½" dia. DCSO Brass Cap on a 1½" O.D. iron pipe protruding
11" above ground in an east-west fence line. (1955
DCSO) Fence to south as recorded in 1968 renewal gone.

Accessories Found -

16" now 21" dia. 2 ft. high rotted D.Fir stump, no blazes
or scribing visible, bears N.54°E., 47.0 ft. (1926
Bowker)

12" now 15" dia. 3 ft. high rotted D.Fir stump, scribing
visible "8 29" bears N.10°E., 13.3 ft. (1926 Bowker)

12" now 27" dia. D.Fir with a fully healed double blaze,
bears N.25°W., 4.6 ft. (1955 DCSO)

16" now 16" dia. 3 ft. high rotted D.Fir stump, scribing
"32 CS" visible on unhealed blaze bears S.46½°W., 53.3
ft. (1955 DCSO)

20" now 24" dia. 6 ft. high D.Fir stump with a healed
single blaze and bark scribing "S28" visible, bears
N.86°E., 14.1 ft. (1955 DCSO)

4" now 9" dia. B.Oak with a fully healed single blaze,
bears S.35½°W., 15.5 ft. (1968 DCSO)

New Accessories -

5" dia. D.Fir double blazed and scribed "X BT" bears
S.59°E., 36.0 ft.

7" dia. D.Fir double blazed and scribed "T28S R7W S28 CS
BT" bears N.35°E., 18.3 ft.

FD. BC G. Lang 10/10, M161-28