

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T28-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5788)

Set post cor. secs. 30, 31, 25 and 36, from which
A Hemlock 8" dia., bears N.78°E., 24 lks. dist.
A Fir 16" dia., bears N.10°W., 18 lks. dist.
A Fir 16" dia., bears S.35°W., 47 lks. dist.
A Fir 12" dia., bears S.40°E., 55 lks. dist.

BLM Resurvey by William W. Glenn, Cadastral Surveyor, under Group #'s 350 and 420, surveyed April/June 1959 - (DCSO records Vol. 30 Page(s) 12851)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 ½" dia., 26" in the ground, with brass cap mkd:

T 28 S
R 9 W | R 8 W
S 25 | S 30
S 36 | S 31
1959

from which

A Fir 7" dia. bears N.22¼°E., 51½ lks. mkd T28S R8W S30 BT
A Fir 7" dia., bears S.31½°E., 15 lks. mkd T28S R8W S31 BT
A Fir 15" dia., bears S.46°W. 67½ lks. mkd T28S R9W S36 BT
A Cedar 11" dia., bears N.58 3/4°W., 53½ lks. dist. mkd.
T28S R9W S25 BT.

Fd. and Used in BLM resurvey by John Jelley, Cadastral Surveyor, Group #552, surveyed July. 1964 - (DCSO records Vol. 32 Page(s) 13573)

Tony Hostetter - For: Roseburg Resources Co. Co. - May 2005 - C.S. File 65/54-18

Found - 1959 BLM brass cap & 2 BTs
21" W.Fir, face evident BT tag, bears N.22¼°E., 34.0 ft. to center
22" Cedar, face evident BLM tag, bears N.58¾°W., 35.3 ft. to center.
New - 18" Fir, scribed "S31BT" bears S.24°29'E., 26.5 ft., to 6" spike placed in root collar.
20" Cedar, scribed "S36 BT" bears S.60°25'W., 11.1 ft. to 6" spike placed in root collar.

continued next page

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T28-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by George M. Winter, Cadastral Surveyor, group No. 2500 Admin File No. 1303, surveyed March/May 2013 - (DCSO records BLM Plat T28-8W, 2014-1 & Vol. 58 Page 23053)

The cor. of secs. 25, 30, 31, and 36, on the W. bdy. of the Tp., perpetuated by Hostetter, in 2005, monumented with an iron post, 2½" dia., firmly set, projecting 3" above ground, with brass cap (properly) mkd.

from which the remaining BTs mkd. by Glenn in 1959

A fir, 22" dia., bears N. 22¼°E., 33.3 ft., with a healed blaze. (Record, 34.0 ft.)

A cedar, 21" dia., bears N.60°W., 34.6 ft., with a healed blaze. (Record, N.58¼°W., 35.3 ft.)

and bearing trees mkd. by Hostetter

A fir, 18" dia., bears S.24½°E., 27.6 ft., with a healed blaze.

A cedar, 20" dia., bears S.60¼°W., 12.0 ft., with fragmentary scribe marks visible on an open blaze.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 12/3/2014 - C.S. File 65/87-21

Condition report only

We find a 3¼" brass cap on a 2½" iron pipe, per Glenn, 1959

23" G.Fir, N.25°30'E., 33.47'

23" I.Cedar, N.57°30'W., 34.82'

19" D.Fir, S.22°E., 27.87'

22" I.Cedar. S.61°W., 12.09'

The remaining BTs of record have been reduced to piles of duff.

Compass decl. 17°E.