

PRIMARY CORNER DESCRIPTION Sec Cor for 19, 20, 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5822)

Set post 4 ft. long, 5" dia., 1 ft. in ground, for cor. of secs. 19, 20, 29 and 30, from which
A Fir 40" dia., bears N.65°E., 32 lks. dist.
A Fir 36" dia., bears N.30°W., 16 lks. dist.
A Fir 28" dia., bears S.60°W., 18 lks. dist.
A Hemlock 10" dia., bears S.55°E., 11 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy and crew -Nov. 22, 1963 - C.S. File 52/79-17

Found original BTs, except SE. BT. NE. BT shows bark scribing on old stump. SW. BT, now snag with large log against face. NW. BT, low cut stump.
Set Brass cap at cor. mkd: County Surveyors Office
T 28 S R 8 W
S 19 | S 20
S 30 | S 29
1963

New BTs- 5" R.Fir bears N.35°E., 29.3 ft. scribed S20 CS BT
10" Hemlock bears S.77°W., 55.6 ft. scribed S30 CS BT T28S R8W.
12" Hemlock bears N.69°W., 30.3 ft. scribed S19 T28S R8W CS BT.
10" Cedar bears S.2°E., 38.8 ft. scribed S29 T28S R8W CS BT.

Fd. and used in BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15086)

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - R.W. Smith; S.J. Flauser, crew - Oct. 8, 1985 - C.S. File 62/29-9 - Also C.S. File 62/29-10 for R. Geisler 8/1985 rpt

Found - 1963 DCSO disk on a I.P. protruding 15" above ground mkd. T28S S19 S20 S30 S29 R5W 1963.
Orig. BT, 40" now a 43" dia. 5 ft. high D.Fir stump with a flat bark blaze and axe marks "X" that do not appear to be orig., bears N.65°E., 24.0 ft. (Rec. N.65°E., 21.1 ft.)
36" now a 42" dia. 4 ft. high D.Fir stump, no marks visible bears N.20°W., 11.4 ft. (Rec. N.30°W., 10.6 ft.) Orig. (Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias	Description

28" now a 30" dia. 25 ft. high D.Fir snag, previously opened, no marks visible, bears S.60°W., 11.9 ft. (agrees w/record) Original. SE. BT gone.

5" now a 10" dia. D.Fir with a fully healed single blaze bears N.32°E., 29.3 ft. (Rec. N.35°E., 29.3 ft.)

10" now a 20" dia. Hemlock with a fully healed single bears S.77°W., 55.6 ft. (agrees w/rec)

12" now a 15" dia. Hemlock with a fully healed double blaze, bears N.69°W., 28.8 ft. to center of root crown (Rec. N.69°W., 30.3 ft. to center of trunk)

10" now a 21" dia. I.Cedar with a fully healed double blaze, bears S.2°E., 38.8 ft. (agrees w/rec.)

The "5" in R5W stamped out and remarked with an "8" to correct range on brass disk.

No new accessories. Corner lies on a West slope. Using orig. dist. as face measurements would move 1963 corner position approx. 15" NE. of present location. I don't believe the possible position difference is significant enough to set another monument.

Fd. OK by McLind, June 1998 - M 128-76