

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 241700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only, T27½-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12863)

Point for the ¼ sec. cor. of sec. 32 only, on the S. bdy. of T27½S R8W.

Set an iron post 28" long, 2½" dia., 14" in the ground, and in a mound of stone 3 ft. base, to top, with brass cap mkd:

T 27½ S R 8 W
¼ S 32
1961

from which

A Hemlock 18" dia., bears N.61°E., 103 lks. mkd. ¼ S32 BT.

A Cedar 20" dia., bears N.69°W., 25 lks. mkd. ¼ S32 BT.

Douglas County Surveyors Office - Gary L. Langlitz; L.E. Monrean; Steve J. Flause, crew - Aug. 31, 1977 - C.S. File 59/38-24

Found - A 2½" x 28" I.P. with 1961 BLM brass cap attached mkd. as noted in 1961. Cap is 24" above ground and leaning. Bearings and distances to BTs indicate that cap is not in original position.

18" now 22" Hemlock stump bears N.61°E., 68.0 ft. Scribing "S32 BT" visible on remaining partially healed blaze.

20" Cedar now 19" stump bears N.69°W., 16.5 ft. scribing "¼ S32 BT" visible on partially healed blaze.

We replaced monument, previously described, at ¼ corner position as referenced from BTs. Monument set 16" deep and added marks "RESET 1977" to brass cap. Mound of stone around monument.

No new accessories. Corner is on steep easterly slope in logged off area.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2500 admin file No. 1201, Surveyed April/May 2012 - (DCSO records Survey plat 2012-1 A&B & Vol. 58 Page(s) 22763-4)

The standard ¼ sec. cor. of sec. 32 perpetuated by the Douglas County Surveyor's Office in 1977, subsequently perpetuated by Hostetter, PLS No. 1975, in 2005, monumented with an iron post 2½" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd.

continued next page

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 241700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only, T27 $\frac{1}{2}$ -8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of a BT mkd by DCSO
A sawed, decayed fir stump, 69" dia., bears S.10°W., 38.4 ft. with no marks visible, and a square-shanked spike driven at the top in the center of the stump, mkd BO 1 and BTs mkd by Hostetter
A fir, 17" dia., bears N.16 $\frac{1}{2}$ °E., 11.3 ft. with fragmentary scribe marks visible on partially healed blaze.
A fir 20" dia., bears S.12 $\frac{3}{4}$ °E., 13.2 ft. with no marks visible on a partially healed blaze.
and a new BT
A fir, 11" dia., bears N.80 $\frac{3}{4}$ °W., 43.4 ft., mkd: X BT.
Add a collar of stone around the iron post.
Corner is located 90 ft. W of a gravel road, 19 ft. wide, bears N.75°W., and S75°E.
(NAD 1983 (Cors 96))
Latitude - 43°10'15.22" N Longitude - 123°40'26.33"W