

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 600360

PRIMARY CORNER DESCRIPTION North 1/16 Cor. Secs. 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Glen Baughman - For: Larry Thomas - Jan. 1973 revised April 1978 - M 49-10 & M 70-6

Set 5/8" iron rod (at proportionate distance)

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/25/2000 - C.S. File 66/14-10

Found - 5/8" iron rod 12" below ground.
26" dia., Cedar with a healed scar. 1972 BT tag "S.33½°E., 43.0 ft."
17" dia., Cedar stump with a healed scar. 1972 BT tag "S.44°W., 21.0 ft."
Area around corner being logged in future rock quarry.

Note - The Above corner set by Baughman, See M 49-10. No mention of BTs.

Set - Two 5/8"x30" long iron rods away from area. (Used Compass bearings)
5/8" x 30" iron rod bears N.15°35'45"E., 810.75 ft.
5/8" x 30" iron rod bears N.28°21'27"E., 589.64 ft.
Bearing between set iron rods N.13°20'03"W., 269.31 ft.
See sketch in file for diagram of set monuments.

Mark Smalley - For: Roseburg Resources - 7/2001 - M 138-50

Looked for, not found in area cleared for rock pit.